

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4212)

Set post, 3" sq. 3 ft. long 24" in the ground for 1/4 sec. cor. mkd 1/4 S on N face, from which
A cedar, 6" dia., bears N.40°E., 24 lks., mkd: 1/4 S BT.
A cedar, 8" dia., bears S.75°E., 28 lks., mkd: 1/4 S BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4335)

The 1/4 sec. cor., the point thereof being determined by measurement from the BTs, no trace of the orig. post being fd. I now perpetuate this cor., as follow: at the exact cor. point. Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor. with brass cap mkd:

S 9
1/4 S 16
1918 from which

A cedar, 10" dia., bears N.67°E., 24 lks., mkd: 1/4 S BT.
(Orig. BT)
A cedar, 12" dia., bears S.61°E., 28 lks., mkd: 1/4 S BT.
(Orig. BT)

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12739-40)

The 1/4 sec. cor. of secs. 9 & 16, remonumented by Mensch in 1918, with an iron post, 1" dia., firmly set, protruding 8" above ground, with brass cap (properly) mkd.

from which the 1883 BTs
A dead cedar, 9" dia., bears N.67 1/4°E., 23 lks., with scribe mark 4 visible on a partially open blaze (Mensch's rec. bears N.67°E., 28 lks.)
A dead cedar, 16" dia., bears S.57 1/4°E., 27 lks., with scribe marks 1/4 S BT visible on a partially open blaze. (Mensch's rec, bears S.61°E., 28 lks.)
add two new BTs
A fir, 9" dia., bears N.16 1/2°E., 31 lks., mkd: 1/4 S9 BT.
A fir, 9" dia., bears S.33 3/4°E., 110 lks., mkd: 1/4 S16 BT.

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 340500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #990, surveyed Aug/Sept 1979 - (DCSO records Vol. 44 Page(s) 16942)

The ¼ sec. cor. of secs. 9 & 16, monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd.

from which the remains of the original bearing trees

A roothole, bears N.67¼°E., 23 lks., alongside of which is a cedar, 10" dia., no marks visible.

A roothole, bears S.57¼°E., 27 lks., alongside of which is a cedar, 16" dia., no marks visible.

and the remains of bearing trees mkd. by Zirpel and Glenn

A fir snag, 9" dia., bears N.16½°E., 31 lks., with scribe marks ¼ S9 BT on open blaze.

A roothole, bears S.33¾°E., 110 lks., with downed fir alongside, 9" dia., no marks visible.

and new bearing trees

A fir, 16" dia., bears N.48½°E., 81 lks., mkd. ¼ S9 BT.

An oak, 8" dia., bears S.1½°E., 55 lks., mkd. ¼ S16 BT.

Fd. Ok by D. Edwards, 1/2000 - M134-15