

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 372273

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 22 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set - 5/8" x 36" steel rebar with 2½" dia., alum. cap.
6" dia., cedar bears S.50°E., 14.2 ft. Scribed "S22 BT"
11" dia., Fir bears N.29°W., 22.9 ft. Scribed "S22 BT"
Note- No trees available in sec. 22 due to slide.
6 ft. steel posts bears North 2 ft. & East 2 ft.)

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff
Lorsung- 5/11/2023 - C.S. File 67/56-16

Found - 5/8" I.Rebar with 2½" alum cap (properly mkd) up 6"
Mostly burned away 6"x1.5 ft. cedar stub S.50°E.,
14.2 ft.
Sawn burnt 14"x6 ft. D.Fir stump N.29°W., 22.3 ft
(rec. 22.9 ft) healed single blaze.
6 ft. steel posts bears North 2 ft and east 2 ft.
New - Burned broken off 60"x6 ft cedar stump S.56°W., 20.0
ft., 3½" mag nail right side center.
Sawn, burned 32"x3 ft D.Fir stump N.4½°W., 23.4 ft.
3½" mag nail top center.
Note - Corner is on very steep rocky north slope in burned
young reprod.
Area burnt 9/2020
Compass decl. 14½°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 164784.289
E 270685.426