

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T27-2

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by S.C. Flint, Contract #459, dated August 3, 1882 - (DCSO records Vol. 10 Page(s) 4183)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 3, 4, 33 and 34, marked T26S R2W S34 on NE.; T27S R2W S3 on SE.; T27S R2W S4 on SW.; T26S R2W S33 on NW. faces, with 3 notches on E. and W. edges of post, from which
A Fir 24" dia., bears N.40°E., 21 lks. dist. mkd. T26S R2W S34 BT.
A Laurel 6" dia., bears S.75°E., 50 lks. dist. mkd. T27S R2W S3 BT.
A Laurel 6" dia., bears S.60°W., 34 lks. dist. mkd. T27S R2W S4 BT.
A Fir 30" dia., bears N.72°W., 33 lks. dist. mkd. T26S R2W S33 BT.

GLO survey by C.M. Collier, Deputy Surveyor, under Instructions dated May/Sept. 1913 - (DCSO records Vol. 10 Page(s) 4260-61)

The Sec. cor. which is a Cedar post, badly decayed, witnessed by the NE. and NW. bearing trees as described by the surveyor general; all other traces of the cor. have disappeared. I destroy this corner and re-establish it in the same place, as follows:
Set a Cedar post 3 ft. long, 4" sq., 24" in the ground, mkd. T26S S34 on NE.; R2W S3 on SE.; T27S S4 on SW.; and S33 on NW. faces, with 3 notches on E. and W. edges; from which
A Fir 24" dia., bears N.40°E., 21 lks. dist. mkd. T27S R2W S34 BT. (Orig. BT)
A Laurel 8" dia., bears S.78°30'E., 33 lks. dist. mkd. T27S R2W S3 BT.
A Fir 36" dia., bears S.78°30'W., 76 lks. dist. mkd. T27S R2W S4 BT.
A Fir 30" dia., bears N.72°W., 33 lks. dist. mkd. T26S R2W S33 BT. (Orig. BT)

BLM Resurvey by Harold D. Corbin, Cadastral Surveyor, under Special Instructions dated June 21, 1957 - (DCSO records Vol. 29 Page(s) 12205)

The Sec. cor., monumented with a Cedar post 4x4 ins. in cross section, 12" above ground, firmly set, mkd. T26S S34 on N.; R2W on S.; T27S S3 on E. and S33 on W. face; from which the original bearing trees as follows:
A Fir 38" dia., bears N.40°E., 21 lks. dist. with scribe marks T26 R2W S34 visible on opened blaze.
(Cont. Next Page)

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T27-2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Madrone 10" dia., bears S.78½°E., 33 lks. dist. with scribe marks T27S R2W visible on opened blaze.

A Fir 48" dia., bears S.78½°W., 76 lks. dist., with a healed blaze.

A Fir 46" dia., bears N.72°W., 33 lks. dist., with scribe marks R2W visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap mkd:

T26S R2W
S 33 S 34
S 4 S 3
T27S
1957

from which

A Madrone 14" dia., bears N.71 3/4°E., 82 lks. dist. mkd. T26S R2W S34 BT.

A Fir 17" dia., bears S.33¼°E., 39 lks. dist. mkd. T27S R2W S3 BT.

A Fir 6" dia., bears S.31°W., 83 lks. dist. mkd. T27S R2W S4 BT.

A Fir 9" dia., bears N.27½°W., 30 lks. dist. mkd. T27S R2W S33 BT.

Deposit cedar stake alongside iron post.

Fd. and used in BLM Resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #990, Surveyed Aug/Sept. 1979 - (DCSO records Vol. 44 Page(s) 16939)

Fd. Ok by B. Shaner - 11/2000 - C. S. File 65/36-2A & M132-70