

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>GLO survey by Wm. N. Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol 10 Page 4231) ----- Set fir post, 3 ft. long, & 4" sq., 24" in the ground for the 1/4 sec cor marked 1/4 S 33 on W face & 34 on E face, from which: A cedar, 14" dia., bears S.79°E., 33 lks., mkd: 1/4 S34 BT. A fir, 14" dia., bears S.64°W., 58 lks., mkd: 1/4 S33 BT.</p>
<p>GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4311-2) ----- 1/4 sec. cor., established by Deputy Gibb in 1909, which is a fir post, 4" sq. 12" above ground, marked & witnessed as described by the survey general.</p>
<p>Thomas E. Shrum Jr. - For: Champion International Co. - Feb. 1, 1979 - M76-56 ----- Found - 24" D.Fir, S.64°W., 38.3 ft. Set - 2 1/2" alum cap. BT - 18" D.Fir S.26°E., 28.6 ft. Note - 1/4 Cor. set from BT established by Gibb in 1909</p>
<p>BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #990, surveyed Aug/Sept 1979 - (DCSO records Vol. 44 Page(s) 16940) ----- The 1/4 sec. cor. of secs. 33 & 34, perpetuated and recorded by Shrum, in 1978, monumented with an iron pipe, 3/4" dia., firmly set, projecting 6" above ground, with aluminum cap mkd. RE 4287 1/4 COR T26 S S 33 S 34 R 2 W 1978 from which the remains of an original BT A fir, 22" dia., bears S.67°W., 58 lks., with scribe marks BT visible on opened blaze. (Record, S.64°W.) and a BT mkd. by Shrum A fir, 16" dia. bears S.20 1/2°E., 43 1/2 lks. with scribe marks 1/4 S34 BT visible on open blaze & a tag mkd. RE 4287.</p>
<p>Fd. Ok by B. Shaner, 1/2001 - C.S. File 65/36-2C & M132-70</p>
<p>continued next page</p>

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 9/29/2022 - C.S. File 67/55-3

Found - 2½" alum. cap, up 12". Add rough stone mound around base. (Properly mkd)
Burned-sawn 12"x3 ft Fir stump S.64°W., 37.5 ft (rec S.67°W., 38.3) add 3½" mag nail top center. OBT
Very burnt 11"x11 ft. Fir snag S.25°E., (rec. S.20½°E.) 28.6. Add 3½" mag nail right side center, blaze gone. 1979
New - 37" D.Fir N.2½°E., 33.5 ft., 3½" Mag nail right side center.
19" I.Cedar N.59°E., 34.8 ft., 3½" mag nail right side center.
25" D.Fir S.4½°W., 34.5 ft., 3½" mag nail right side center.
All trees alive, base bark burned.
Note - Cor is on moderate SE slope 175'± North of gravel rd
Area burnt 9/2020
Compass decl. 14½°E.

OCRS Coordinate system
Cottage Grove - Canyonville Zone NAD 88
N 157325.148
E 271159.790