

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400273

PRIMARY CORNER DESCRIPTION CC Secs. 27 & 28 only (North)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. N. Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol 10 Pg 4329 & 4233-4)

Page 4329 The closing cor. of secs. 27 & 28 established by me in 1916, which is an iron post, 3 ft. long, 2" dia., 12" above ground, marked & witnessed as described by the surveyor general. I now destroy this cor.

Page 4233-4 Set a granite stone 6x8x14", 10" in the ground for cor. for cor. of secs. 21, 22, 27, & 28 marked with 3 notches on E & 2 notches on S edges, from which

- A laurel, 10" dia., bears N.49°E., 39 lks., mkd: T26S R2W S22 BT.
- A cedar, 30" dia., bears S.15°E., 43 lks., mkd: T26S R2W S27 BT.
- A maple, 7" dia., bears S.12°W., 75 lks., mkd: T26S R2W S28 BT.
- A laurel, 8" dia., bears N.18°W., 33 lks., mkd: T26S R2W S21 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4329-30)

Intersect new S bdy of sec. 22. At the point of intersection. Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for closing cor. of secs. 27 & 28, with brass cap mkd:

T26S R2W
S 22

S 28 | S 27
CC
1918

from which

- A fir, 6" dia., bears S.3°E., 14 lks., mkd: C C T26S R2W S27 BT.
- A fir, 10" dia., bears S.12°W., 14 lks., mkd: C C T26S R2W S28 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug 1967 - C.S. File 54/40-60

Found - GLO brass cap, properly marked in 1917
10" D.Fir, now 22" S.12°W., 9.2 ft. shows good face.
New BT - 10" D.Fir, S.86½°E., 25.8 ft. scribed T26S R2W S27
CC CS BT

FD. Ok by D. Edwards 2/2004 - M143-66 _____cont.

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400273

PRIMARY CORNER DESCRIPTION CC Secs. 27 & 28 only (North)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 8/6/2024 - C.S. File 67/58-44

Found - 2½" GLO brass cap (properly mkd) up 10"
Burned, broken 12"x6' D.Fir snag, S.86½°E., 25.8 ft.
fully healed single blaze, add 3½" mag nail right
side center.
2 metal post; 1 ft. South, 2 ft West.
New - Burned, sawn, 32"x3 ft. D.Fir stump, N.56°E., 9.2
ft., 3½" mag nail top center.
Note - Mon in burned over young reprod unit on steep NNE
slope approx. 150' north of gravel road.
Area burnt 9/2020
Compass decl. 14¼°E.
Oregon Coordinate Reference System
Cottage Grove - Canyonville Zone
N 164785.760 E 271186.098