

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4209-10)

Set post, 3 ft. long, & 3" sq., 24" in the ground for the 1/4 sec. cor. marked 1/4 S on W face, from which:
A fir, 8" dia., bears N.10°W., 31 lks., mkd: 1/4 S BT.
A fir, 8" dia., bears S.18°E., 21 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12736)

Point for the 1/4 sec. cor. of secs. 3 & 4, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 26" in the ground with brass cap marked: T26S R2W

1/4
S 4 | S 3
1959

from which

A fir, 20" dia., bears S.47 1/2°E., 23 lks., mkd: 1/4 S3 BT.
A fir, 26" dia., bears S.73 3/4°W., 63 lks., mkd: 1/4 S4 BT.

Ron Quimby - Crew: N. Fromdahl, L. Heddens & J. Ogden - 10/2020 - C.S. File 65/106-60

Found - 1959 BLM brass cap (properly marked)
Down, burnt fir S.47 1/2°E., 15.2'
Root hole S.74 3/4°W., 41.6'

New - 5/8"x30" I.Rods with yellow plastic cap stamped "ie ENGINEERING" with post alongside:
N.79°E., 6.9' S.40°E., 6.8'
S.44°W., 7.6' N.53°W., 7.0'

Note - Compass decl. 15 1/2°E.
Area badly burnt 9/2020

Douglas Co. Surveyors Office - Crew: Stephen Flaue & Jeff Lorsung- 3/3/2022 (Filed 4/14/2022) - C.S. File 67/52-15

Found - BLM brass cap - properly marked.
5/8" Iron rods with yellow plastic cap stamped: ie ENGINEERING
N.72°E., 7.1 (Rec. N.79°E., 6.9)
S.51°W., 7.0 (Rec. S.44°W., 7.6)
S.46 1/2°E., 6.8 (Rec. S.40°E., 6.8)
N.53°W., 7.0 (Rec. N.49°W., 6.9)
1959 BLM BT burnt to ground, Fir S.47 1/2°E., 15.2 ft.

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Note - Area burnt 9/2020
Corner is on large flat bench approx 275' east of
gravel road on N-S cutting line.
Old growth to east burnt clear cut to west.
Compass decl. $14\frac{1}{2}^{\circ}$ E.
See sketch in file.
Lat: $43^{\circ}20'10.27''$ N Long: $122^{\circ}55'54.59''$ W