

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page 4224)

Set granite stone, 5x9x14", 10" in the ground for sec. cor., marked, on W. face, from which
A cedar, 50" dia., bears N.54°E., 36 lks., mkd: ¼ S35 BT.
A fir, 8" dia., bears S.74°W., 24 lks., mkd: ¼ S34 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4310)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor., with brass cap mkd:

¼
S 34 | S 35
1916

from which

A hemlock, 18" dia. bears S.55°30'E. 32 lks. mkd: ¼ S35 BT
A cedar, 24" dia., bears N.80°W., 29 lks., mkd: ¼ S34 BT.
The cor. established by Deputy Gibb in 1909 as the cor of secs, 34 & 35, which is a granite stone, 4x9x5" above ground, firmly set, marked and witnessed as described by the surveyor general, bears S.83°10'E., 2,06 chs.

I destroy the corresponding cor. set in the rejected revision survey and marks on bearing trees

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug. 10, 1967 - C.S. File 54/40-40

Found - 1916 GLO brass cap, firmly set, properly mkd.
Uprooted stump of 24" cedar N.80°W., 19.1 ft. now lying north of corner, scribing visible on open blaze.

No trace of other BT.

New BTs- 16" hemlock S.25°E., 110.9 mkd. ¼ S35 CS BT.

No trees available in sec. 34.

Note - This corner lies 12.5 ft. N of the #3 corner of Tract 38 on steep E slope 100 ft. W of temporary log road.

BLM dependent resurvey by Dale T. Bedell & Bryan S. Seibold, Cadastral Surveyors & Robert H. Browning, Survey Technician, under Group No. 1638, surveyed July 1992/April 1995 - (DCSO records Vol. 51 (Page(s) 19756)

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

The 1/4 sec. cor. of secs. 34 and 35, perpetuated by Vernon Ray Tracy, Deputy County Surveyor, in 1967, and utilized by Thomas E. Shrum, Jr., Registered Land Surveyor No. 1706, in 1979, recorded in Douglas County Surveyor's Office map file M76-56; monumented with an iron post, 1 in. diam., firmly set, projecting 4 ins. above the ground, with brass cap mkd.

1/4 S 34 | S 35
1916

from which a bearing tree mkd. by Tracy

A hemlock, 24 ins. diam., bears S. 26° E., 168 lks. dist., with scribe marks S35 CS BT visible on a partially healed blaze.

and a new bearing tree

A cedar, 4 ins. diam., bears N. 16¼° W., 38 lks., mkd. X BT.

Bruce Shaner - 11/2000 - C. S. File 65/36-2M & M132-70

Found - 2½" brass cap, properly mkd., on a 1" I.P.
28" Hemlock, scribes visible, bears S.26°E.
110.9 ft

6" Cedar, face overgrown, bears N.16¼°W., 25.1 ft.

2½" brass cap on I.P., SW corner to Tract 38, bears South, 12.5 ft.

New BT - 6" Red Cedar, scribed "¼ S S34 BT" bears N.75°W., 7.3 ft.

Note - Corner lies at bottom of small bluff in rock.
Compass declination 20°E.

Fd. Ok by Tony Hostetter, 10/2002 - M141-16