

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION West Sec Cor Secs 23 & 26, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4198-9)

Set a post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 22, 23, 26, & 27, marked T26S S23 on NE, R2W S26 on SE, S27 on SW, S22 on NW faces, with 2 notches on S & E edges; from which

- A fir, 12" dia. bears N.45°E. 11 lks. mkd: T26S R2W S23 BT
- A hemlock, 18" dia., bears S.60°E., 55 lks., mkd: T26S R2W S26 BT.
- A cedar, 18" dia., bears S.30°W., 43 lks., mkd: T26S R2W S27 BT.
- A fir, 10" dia. bears N.20°W. 10 lks. mkd: T26S R2W S22 BT

GL0 survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4227)

Intersect E and W line, 9.27 ohs. E of cor. secs. 22, 23, 26 & 27, which is a stake marked & witnessed as described by the Surveyor General.

Set granite stone, 6x7x14", 10" in the ground for closing cor. secs. 26 & 27, marked with 2 grooves on E & 4 grooves on W face; from which

- A hemlock, 7" dia., bears S.52°E., 32 lks. Marked T26S R2W S26 BT.
- A hemlock, 12" dia., bears S.55°W., 15 lks. Marked T26S R2W S27 BT

I destroy markings on other cor. and bearing trees referring to secs. 26 and .27.

At this cor. set off 12°09'N. on decl. arc and at 0 hrs. 3m. p.m. 1. m. t. observe the sun on the meridian; the resulting latitude is 43°17'.

GL0 resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4303 & 4327)

Pg 4303 - Intersect the orig. cor. established by Deputy MoQuinn in 1883, as the cor. of sees. 22, 23, 26 and 27, which is a decayed post, witnessed as described by the surveyor general, except for slight discrepancies in position of bearing trees. The NW bearing tree has been cut down I now perpetuate this cor., as follows: at the exact cor. point Set an iron post, 3 ft. long, 2" dia., 24" in ground, for cor. of secs. 22, 23, 26 and 27, with brass cap mkd:

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION West Sec Cor Secs 23 & 26, only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>T26S R2W (Note: This corner changed to S 22 S 23 refer to secs. 23 & 26 only S 27 S 26 8/10/1945 BBI) 1916</p>
<p>from which A fir, 18" dia., bears N.43°E., 11 lks., mkd: T26S R2W S23 BT. Orig. BT A hemlock, 20" dia., bears S.58°E., 55 lks., mkd: T26S R2W S26 BT. Orig. BT A cedar, 16" dia., bears S.27°W., 45 lks., mkd: T26S R2W S27 BT. Orig. BT A hemlock, 10" dia., bears N.23°W., 90 lks., mkd: T26S R2W S22 BT. from this cor. the established by Deputy Gibb in 1909* as the closing cor. of secs. 26 & 27, on S bdy of sec. 23, which is a granite stone, 4x7x6" above ground firmly set, marked & witnessed as described by the surveyor general, bears S.89°34'E. 9.26 chs. Also the cor. established by Deputy Gibb in 1909 as the closing cor. of sees. 22 & 27, on W bdy, of sec. 23, which is a granite stone, 5x10x8" above ground, firmly set, marked and witnessed as described by the surveyor general, bears N.0°52'E., 14.96 ohs. I destroy the corresponding cor. of the rejected revision survey & marks on BTs. Pg 4327 - ... cor. of sec. 22, 23, 26, & 27, which I change to refer to secs. 23 & 26 only</p>
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - July 1967 - C.S. File 54/40-42 ----- Found - 1918 GLO brass cap, properly marked Orig. 18" now 22" Fir snag, N.43°E., 7.3 ft. shows good scar. No trace of orig. BT in sec. 26. New BTs- 8" Hemlock S.38°E., 3.2 ft. mkd: T26S R2W S26 CS BT. 7" W.Fir, N.55°E., 13.7 ft. mkd: T26S R2W S23 CS BT. Note - This corner lies on large flat bench in very old logged off unit. Obliterated OBT to SW alive.</p>
<p>Fd & used on BLM dependent resurvey by G. Steven Popken, Cadastral Surveyor, Group No. 871, surveyed June/Sept. 1975 - (DCSO Vol. 46 Page(s) 15722-3)</p>
<p>continued next page</p>

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION West Sec Cor Secs 23 & 26, only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22927)

The cor. of secs. 23 and 26 only, monumented with an iron post, 2" dia., firmly set, projecting 8 ins. above ground, with brass cap mkd.

T26S
|S 23
|S 26
R2W
1918

from which the remains of the original bearing trees

A roothole bears N.43°E., 7.3 ft., with a fallen, decayed fir snag, size indeterminate, lying alongside, with no marks visible.

A cedar, 35" dia., bears S.27°W., 29.7 ft., with a healed blaze.

and BTs mkd. by the Douglas County Surveyor's Office in 1967

A hemlock, 14" dia., bears N.55°E., 13.9 ft., with a healed double blaze. (Record, white fir)

A hemlock, 15" dia., bears S.38°E., 3.3 ft., with a healed double blaze

NAD 1983 (CORS 96)

Latitude: 43°16'59.11"N. Longitude: 122°54'48.91"W.

Douglas Co. Surveyors Office - Crew: Stephen Flaue & Jeff Lorsung- 11-3-2021 (Filed 11/23/2021) - C.S. File 67/51-26

Found - Brass cap on 2" Iron Pipe, loose out of ground, reset from NE & SW BTs by Dist-Dist intersection projecting 9" above ground in rough mound of stone. BC properly marked and added "RESET 2021"

A root hole N.43°E., 29.7 ft. (OBT)

Mostly burned 38" Cedar stump S.27°W. 29.7 ft Set 4"

MAG NAIL near top center at bearing & dist. OBT

Dead 15" Hemlock N.55°E., 13.9 ft., healed double blaze, burned base. 1967 DCSO

Uprooted Hemlock, mostly burned, no position.

New - 10" D.Fir N.3°E., 24.4 ft., not scribed.

17"x1½ ft. D.Fir stump, 4" MAG NAIL top and center N.29°W., 37.0 ft.

Note - Area burned by Archie Cr. Fire - 9/2020

Compass decl. 14½°E.