

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4199-4200)

-----

Set cedar post, 3" sq., 3 ft. long, 24" in the ground, for cor. to secs. 14, 15, 22, & 23, marked T26S S14 on NE, R2W S23 on SE, S22 on SW, S15 on NW faces, with 3 notches on S & 2 notches on E edges; from which

- A fir, 12" dia. bears N.55°E. 175 lks mkd: T26S R2W S14 BT
- A fir, 12" dia. bears S.50°E. 86 lks. mkd: T26S R2W S23 BT
- A fir, 12" dia. bears S.70°W. 54 lks. mkd: T26S R2W S22 BT
- A fir, 30" dia. bears N.50°W. 15 lks. mkd: T26S R2W S15 BT

GL0 survey by Wm. N. Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO recs Vol. 10 Pgs 4229)

-----

Cor. secs. 14, 15, 22, & 23, which is a stake greatly decayed, mkd & witnessed as described by the surveyor general Set granite stone, 6x10x15", 10" in the ground for cor. secs. 14, 15, 22, & 23, marked with 2 notches on E & 3 notches on S face.

GL0 resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4305)

-----

Intersect the cor. of secs. 14, 15, 22 & 23, established by McQuinn in 1883, which point is now marked by a basalt stone, 6x8x6", above ground, firmly set, marked with 3 notches on S & 2 notches on E edge, witnessed as described by the surveyor general, except for slight discrepancies in the position of the bearing trees and that the NW tree is dead and the NE tree is dead & fallen. The SW tree, on account of the heavy bearing of the line bet. secs. 15 & 22, is not in the section to which it refers. I re-witness the cor. as follows: from the cor.

- A fir, 12" dia., bears N.51°30'E., 64 lks., mkd: T26S R2W S14 BT.
- A fir, 24" dia., bears S.46°E., 87 lks., mkd: T26S R2W S23 BT. (Orig. BT)
- A laurel, 5" dia., bears S.33°W., 25 lks., mkd: T26S R2W S22 BT.
- A fir, 18" dia., bears N.71°W., 74 lks., mkd: T26S R2W S15 BT.

This cor. was also used as the cor. for the rejected revision survey.

continued next page

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - James W. Byron, Deputy - June 12, 1957 - C.S. File 47/189

-----

Found - 6"x8"x6" stone above ground with 2 notches on E & 3 notches on S & all BTs as recorded by Mensch in 1916 & 1918. All BTs alive. NE BT shows scribe marks - same for SW laurel BT. All check for size, bearing & distance. I also find orig. 12" now 20" fir, S.70°W., 35.6 ft. BT - I do not open shows good face.

Set - Iron pipe with brass cap alongside stone mkd.  
Sec  $\frac{15}{22} | \frac{14}{23}$  T26S R2W, County Surveyors Office 1957

Note - 16" cedar S.1°E., 128.4 ft. mkd S23 T26S R2W CS BT  
Corner renewal requested by Lockwood, who will remove the SE BT.

Fd & used on BLM dependent resurvey by Irving Zirpel, Jr. & Wm. Glenn, Cadastral Surveyors, Group No. 404, surveyed May/Oct. 1959 - (DCSO Vol. 30 Page(s) 12724-5)

BLM dependent resurvey by G. Steven Popken, Cadastral Surveyor, Group No. 871, surveyed June/Sept. 1975 - (DCSO Vol. 46 Page(s) 15724-5)

-----

The cor. of secs. 14, 15, 22, & 23. perpetuated & recorded by Byron, in 1957, monumented with an iron post, 1½" dia. firmly set, projecting 18" above ground, alongside of which the basalt stone. 18x6x6", set by Gibb, in 1909, mkd. with 3 notches on S. and 2 notches on E. edges. The brass cap is (properly) mkd.,  
from which the remains of the orig. BTs  
A Fir, 25" dia. bears S.71½°W., 52½ lks. with healed blaze and BTs by Mensch  
A fir, 15 ins. dia., bears N.51½°E., 65 lks., with healed blaze.  
A broken madrone stump. 7" dia., bears S.35¾°W., 23½ lks., no marks visible on weathered blaze.  
A fir, 26" dia., bears N.70½°W., 75 lks., with healed blaze.  
and a bearing tree mkd. by Byron  
A cedar. 15" dia., bears S.1½°E., 194½ lks., with scribe marks T26S R2W S23 CS visible on open blaze.  
and a bearing tree of no record  
A fir, 11" dia., bears S.35½°W., 67 lks., with healed blaze.

continued next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Fd. cap 4/13/1992 BLM C.S. File 63/140-9

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike  
- 1/6/2004 - C.S. File 67/13-6

-----  
Found - A granite stone measuring approx. 6x10x15" with 2 notches & 3 notches marked on the appropriate faces (1909 Gibb resurvey) is fd loose, & out of position, on ground surface. Stone is near a hole with dimensions similar to base of stone. 1957 DCS0 brass cap not fd.

Accessories fd bearings & dists are measured from westerly edge of fd hole; most fd evidence indicates this was the set position for the 1957 brass cap from which the DCS0 & 1959 BLM bearings & distances were measured. The fd. evidence also indicates the center of the fd. stone when properly oriented in the above fd hole is the corner position established in 1909 by Gibb.

One orig. BT fd., A 12" fir now a 27" DBH D.Fir with fully healed single blaze bears S.71½°W., 34.7' dist. (rec. S.70°W. 35.6') Possible root hole of NW OBT fd no other orig evidence remains.

From the 1916 Mensch resurvey 3 renewal BTs are fd (Following 3 bearings & distances noted as record would be to center of 1909 stone monument)

A 12" Fir now 16" DBH D.Fir with fully healed single blaze bears N.51½°E. 42.9' (rec N.51½°E. 42.2')

5" Laurel now a rotted broken Madrone stump (good root position) with no discernible scribing bears S.34°W., 15.5' (rec. S.33°W., 16.5')

18" Fir now 28" DBH D.Fir with a fully healed single blaze bears N.70½°W., 49.5' (rec. N.71°W., 48.8')

From the 1957 DCS0 renewal 1 renewal BT is fd:  
16" Cedar, now a 16" Incense Cedar with a fully healed double blaze bears S.1½°E., 128.4' (rec. S.1°E., 128.4')

A BT of unknown origin:  
17" DBH D.Fir with an apparent fully healed single blaze (we do not open) bears S.35°W., 44.2' (rec. on fd. BT tag has erroneous reverse bearing S.35°W., and a dist. of 67 lks; survey attributed to "P.O.P.")

New - The previously described fd. stone is set in the fd. hole with 2 notches on one side facing east & 3 notches on another side facing south.  
continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor Secs 14, 15, 22, & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Along the west edge of the above stone is set a 2 3/8" brass cap on a 30" galvanized iron pipe. The stone is set with its top flush with the ground & the brass cap monument protrudes approx 6" above the ground. Cap mkd:  
DOUGLAS COUNTY SURVEYOR  
T26S R2W  
S 15 | S 14  
S 22 | S 23  
2004

Note - No new accessories  
Monument is on gradual southerly facing forested slope.  
Compass decl. 16¾°E.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 7/10/2025 - C.S. File 67/61-25  
-----  
Found - D.C.S.O. brass cap along side granite stone, 6"x10"x15" with 2 notches & 3 notches.  
DOUGLAS COUNTY SURVEYOR  
T26S R2W  
S 15 | S 14  
S 22 | S 23  
2004

Burned dead solid 28" D. Fir. S.71½°W. 34.7 ft.  
17" Fir singed base, N.51½°E. 42.9 ft. Healed single blaze.  
Burned dead solid 30" Fir N.70½°W. 48.6 ft.  
(Rec 49.5 ft.) Healed single blaze.  
16" Cedar singed base S.1½°E. 128.4 ft. Healed double blaze.  
Burned 20" D. Fir. Few live limbs S.35°W. 44.2 ft.  
Healed single blaze.  
Add 3½" mag nail, right side center at 2004 dist to all BT's except S.E. Cedar.

Notes - Area burnt 9/2020  
Compass decl. 14½°E.  
Trimble Geo XT Position  
43°17'57.109" N.  
122°54'47.945" W.