

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 540220

PRIMARY CORNER DESCRIPTION CS 1/16 Sec 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCS0 records Vol. 58 Page(s) 22936)

The Point for the center S 1/16 sec. cor. of sec. 26.
Set a stainless steel post, 28" long, 2½" dia., 7" in the ground to underlying rock, in a mound of stone, 3 ft. base, to top, with brass cap mkd.

C
S 1/16 | S 26
C
2011

from which

A cedar, 10" dia., bears S.31½°E., 24.2 ft., mkd. CS1/16 S26 BT.

A fir, 21" dia., bears S.62°W., 48.9 ft., mkd. CS1/16 S26 BT.

Corner is located 55 ft. N. of a gravel road, 18 ft. wide, bears N.80°E. and S.80°W., and further located 375 ft. E. of the same gravel road, 12 ft. wide, bears N.60°W. and S.60°E.

Douglas Co. Surveyors Office - Crew: Stephen Flauser & Jeff Lorsung- 1/13/2023 - C.S. File 67/55-24

Found - 3¼" BLM brass cap (properly mkd) proj 3" in mound of stone.

Burned dead 13" Cedar S.31½°E., 24.5 ft. (rec. 24.2 ft) face partly healed vis scribed. Add 3½" mag nail right side center.

15"x6' burned fir stub S.62°W., 48.2 ft. (rec. 48.9) with metal rain cap, 3" mag nail right side center.

Note - Area burnt 9/2020

Corner is 55 ft N of a gravel road 18' wide bears N.80°E., & S.80°W., also located 375' E of same gravel road 12' wide bears N.60°W., & S.60°E.

Compass decl. 14½°E.