

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor Secs 11, 12, 13, & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4193-4)

Set post, 4 ft. long, 4" sq., 24" in the ground for cor. of secs. 11, 12, 13, & 14, mkd T26S S12 on NE, R8W S13 on SE, S14 on SW & S11 on NW faces with 4 notches on S and 1 notch on E edges, from which

- A fir, 30" dia. bears N.55°E. 19 lks. mkd: T26S R2W S12 BT
- A fir, 30" dia. bears S.30°E. 22 lks. mkd: T26S R2W S13 BT
- A fir, 40" dia. bears S.55°W. 18 lks. mkd: T26S R2W S14 BT
- A fir, 36" dia bears N.50°W., 139 lks mkd: T26S R2W S11 BT

BLM dependent resurvey by Lynn M. Roseberry, Cadastral Surveyor, Group #664, surveyed April 1968 - (DCSO records Vol. 34 Page(s) 14272)

The cor. of sees. 11, 12, 13, & 14,, determined at record dist. from the remaining original BTs:

- A fir snag, 50" dia., bears S.27°W., 18 lks., with faint evidence of bark scribing visible on remaining portion of original blaze. (Record, S.55°W.)
- A fir, 60" dia., bears N.26°W., 139 lks., with faint evidence of bark scribing visible on remaining portion of original blaze. (Record, N.50°W.)

At the corner point
Set an iron post, 28", long, 2" dia., 24" in the ground, with brass cap marked.

T26S	R2W
S 11	S 12
S 14	S 13
1968	

from which new BTS

- A fir, 12" dia., bears N.57°E., 62½ lks., mkd: T26S R2W S12 BT.
- A fir, 16" dia. bears S.64°E., 63 lks mkd: T26S R2W S13 BT
- A fir, 62" dia., bears S.51½°W., 51 lks., mkd: T26S R2W S14 BT.
- A fir, 12" dia. bears N.48°W. 38 lks. mkd: T26S R2W S11 BT

Ken Hoffine - For: Lone Rock Timber Co. - 10/1999 - M 133-59

Found - 1968 BLM brass cap.

- 18" D.Fir bears N.46½°W. 24.6 ft (rec. N.48°W.* 25.08 ft.) well healed face & BT tag.
- 65" D.Fir bears S.48½°W.* 32.9 ft (rec S.51½°W. 33.66 ft.) well healed face & BLM tag.

(* bearings corrected 6/19/2023 JC DCS0)

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

22" D.Fir bears S.62½°E. 41.5 ft (rec S.64°E. 41.58 ft.) well healed face & BLM tag.
21" D.Fir bears N.57°E., 41.2 ft. (as per rec) well healed face & BLM tag.
Corner lies on SW slope approx. 130 ft. South & 250 ft. West of rock road.

David Edwards - Crew: Brant Miller - 6/13/2023 - C.S. File 65/111-50

Found - 1968 BLM brass capped iron pipe still in the ground but leaning severely, return the pipe to vertical and reference out. Dig a deeper hole and replace the pipe at the original position projecting 6" A 25" dia. Fir stump bears N.57°E., 41.2 ft.
A 27" dia. Fir stump bears S.62½°E., 41.5 ft.
A 66" dia. Fir stump bears S.48½°W., 32.9 ft.
A 25" dia. Fir stump bears N.45½°W., 24.6 ft. (Rec. N.46½°W.)
Place tags on all stumped bearing trees.

Set - 5.5 ft steel posts 2 ft North, 2 ft South, 2 ft East and 2 ft West.

Note - This corner lies within the footprint of the 2020 Archie Creek fire.
Compass Declination 15° East

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/2023 - C.S. File 67/57-22

DCSO visited between Edward's renewal and it being filed. Our crew found the bearings on his renewal basically the same so we will not type our report.
4 steel posts around monument, 1 in each quadrant, 2 ft away. Mon. on SW slope approx. 130' south & 250' west of gravel rd.
Compass decl. 14½°E.
Lat: 43°18'49.72"N Long: 122°53'37.06"W