

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 9 Page(s) 3579)

Set Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor. mkd. ¼ on N. face, from which

A Fir 36" dia., bears N.60°E., 35 lks. dist. mkd. ¼ S BT.

A Fir 36" dia., bears S.5°W., 67 lks. dist. mkd. ¼ S BT.

GLO survey by C.M. Collier, Deputy Surveyor, under Instructions dated May 12, 1913, Surveyed Sept. 1913 - (DCSO records Vol. 10 Page(s) 4267)

The ¼ sec. cor. of sec. 1, located by reference to the bearing trees as described by the surveyor general: All other traces of the cor. have disappeared. I re-establish this cor. in its original position as follows:

Set a basalt stone 18x10x8 ins., 12" in the ground for ¼ sec. cor. of sec. 1 only, marked ¼ on N. face, witnessed by the original bearing trees as follows:

A Fir 36" dia., bears N.60°E., 35 lks. dist. The facing was only in the brk and is nearly burned away.

A Fir 36" dia., bears S.5°W., 67 lks. dist. mkd. in the bark, ¼ S BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Aug. 1967 - C.S. File 54/40-75

Found - Basalt corner stone 18" x 10" x 8" mkd. ¼ on S. side, firmly set by Collier in 1913.

Orig. 36" now 48" Fir, alive, S.5°W., 44.2 ft., shows "¼S" bark scribe.

Orig. 36" now 50" Fir, alive, N.60°E., 25.1 ft. (Rec. 23.1 ft.) shows edge of old axe bark blaze and possible fragmentary scribe marks.

Set Brass cap at cor. mkd: County Surveyors Office
(Reset stone alongside) T25S
T25S R2W ¼ S 1
1962

New BTs- 14" D.Fir S.36°E., 23.0 ft. mkd. ¼ S1 CS BT.
16" D.Fir S.53°W., 4.3 ft. mkd. ¼ S1 CS BT.

Cor. lies on very steep West slope approx. 220 ft. East of small creek, course SW.

continued next page

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 640700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor
Under Group No. 2317, Surveyed June 2010/June 2011 - DCSO
records Vol. 57 Page(s) 22782

The ¼ sec. cor. of sec. 1 only, T26S R2W perpetuated by the
Douglas Co. Surveyors Office in 1967, monumented with an iron
post, 2" dia. firmly set, projecting 10" above the ground
(along the S. side of which is the original stone, 18x10x8",
with no marks showing), with brass cap (properly) mkd.
from which the remains of the original bearing trees

A sawed, decayed fir stump, 41" dia., bears N.54°E., 26.0
ft., with no marks visible. (Record, N.60°E., 23.1 ft)

A sawed fir stump, 46" dia., bears S.26½°E., 44.2 ft., no
marks visible. (Record, S.5°W.)

and the remains of BTs mkd by the Douglas Co. Surveyors
Office

A sawed fir stump, 19" dia., bears S.35½°E., 22.7 ft.,
with a healed blaze.

A fir snag, 21" dia., bears S.50¼°W., 4.2 ft., with a
healed blaze.

and new bearing trees

A fir, 5" dia., bears N.72°E., 13.5 ft., mkd. ¼ S1 BT.

A fir, 6" dia., bears S.8¼°E., 21.8 ft., mkd. X BT.