

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 25 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 10 Page(s) 4064)

Set Hemlock post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. corner marked ¼ S on W. face, from which

A Hemlock 6" dia., bears N.65°E., 18 lks. dist. mkd. ¼ S BT.

A Hemlock 10" dia., bears N.55°W., 23 lks. dist. mkd. ¼ S BT.

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4088) and (4089)

(Page 4088)

The ¼ sec. cor. between secs. 25 and 30 is not found after careful search. Set temp ¼ sec. cor.

(Page 4089)

Set a basalt stone 15x8x6 ins., 10" in the ground for ¼ sec. cor. on E. bdy. of sec. 25, T26S R2W, marked ¼ on W. face, from which

A Cedar 14" dia., bears S.55°W., 44 lks. dist. mkd. ¼ S25 BT.

A Cedar 16" dia., bears N.78°W., 24 lks. dist. mkd. ¼ S25 BT.

GLO Survey by Fred Mensch, U.S. Surveyor Under Special Instructions dated May 25, 1916 - (DCSO records Vol. 10 Page(s) 4282-83)

Intersect the original ¼ sec., established by Deputy McQuinn in 1883; this cor. is a Hemlock post, partly burned, has evidently fallen over and been recently reset, but at proper point as shown by the bearing trees, which are as described by the surveyor general.

I now perpetuate this cor. by setting an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ cor. of sec. 25 only, in place of old post, now too badly delapidated for further use, with brass cap marked:

¼
S25
1916

from which

A Hemlock 8" dia., bears S.58°W., 37 lks. dist. mkd. ¼ S25 BT.

A Hemlock 10" dia., bears N.55°W., 24 lks. dist. mkd. ¼ S25 BT.

(Cont. Next Page)

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 700240

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 25 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

I now destroy the corresponding cor. of the rejected revision survey and marks on bearing trees.
The cor. established by Deputy Mensch in 1910 as the ¼ cor. of said sec. 25 (which is a basalt stone, 15x8x6 ins., firmly set, marked and witnessed as described by the surveyor general) bears N.40°27'W., 80 lks. dist. I now destroy this cor. and marks on bearing trees.

Fd OK DCSO, VRT Aug. 1967 - C.S. File 54/40-46