

TOWNSHIP 26 RANGE 03E POINT IDENTIFIER # 400140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Otto L. Draper, US Transitman under Special Instr. dated Dec. 27, 1920, Group No. 64; surveyed Aug. 1930/June 1931 - (DCSO records Vol. 23 Page 9776)

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked

1/4
S33|S34
1930

from which

- A fir, 38" dia., bears S.36°E., 26 lks., mkd: 1/4 S34 BT.
- A cedar, 12" dia., bears N.42°W., 20 lks., mkd: 1/4 S33 BT.

Douglas Co. Surveyors Office - Dennis Gaylord, USFS & Deputy Co. Surveyor - Walter Barton - May 19, 1977 - C.S. file 59/34-20

Found - 40" D.Fir stump, partly decomposed, open & find scribing & reverse "S34 BT", bears S.36°E., 17.16 ft.

BT to the NW has been destroyed when Fish Creek Canal was built. It lies in borrow area.

Orig. GLO brass cap apparently destroyed in logging operations.

Set - 2 1/2" Brass cap on a 1" gal. I.P. stamped: County surveyor's Office T26S R3E 1/4 S33 S34 1977., from found BT stump.

Brass cap is 8 ft. east of top of borrow area cut, and 200 ft. ± east of Fish Creek Canal.

New BTs- A 58" D.Fir bears N.81°E., 36.4 ft. scribed "1/4 S34 CS BT" on a single blaze.

A 11" D.Fir bears N.74 1/2°W., 298.3 ft. scribed "1/4 S33 CS BT" on a double blaze. This BT is approx. 25 ft. west of canal.

Note - Declination (18°) determined at Cor Sec. 28, 27, 33 and 34.

A line south to this corner falls 30(± or °)E of the corner.