

TOWNSHIP 26 RANGE 03E POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Otto L. Draper, US Transitman under Special Instr. dated Dec. 27, 1920, Group No. 64; surveyed Aug. 1930/June 1931 - (DCSO records Vol. 23 Page 9757)

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked

1/4 S13
S24
1930

from which

A fir, 30" dia., bears N.48°E., 88 lks., mkd: 1/4 S13 BT.
A pine, 26" dia., bears S.3°W., 62 lks., mkd: 1/4 S24 BT.

Douglas Co. Surveyors Office - Dennis Gaylord, USFS & DCSO Deputy - Randal Lopez - May 11, 1978 - C.S. File 60/11-7

Found - Orig. brass cap set in 1930 has been destroyed by logging operations.

Orig. 30" now 34" D.Fir stump bears N.48°E., 58.08 ft. Open & find scribing & reverse "BT"

Orig. Pine to the SW has been destroyed by road construction.

Set - Using the orig. Fir BT stump as reference, I SET a 2 1/2" brass cap on a 1" I.P. stamped County Surveyors Office T26S R3E 1/4 S13 S24 1978.

A 25" D.Fir bears N.14°E., 80.1 ft. scribed "1/4 S13 CS BT" on a double blaze.

A 9" R.Fir bears S.35°30'W., 108.3 ft. scribed "1/4 S24 CS BT" on a double blaze. This BT is across road #2687. (on south side)

Placed BT signs on both trees. Corner is 30 ft. North of F.S. Rd. #2678.