

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION ¼ Sec. Cor. for 5; & 32 of T.25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855  
(DCSO Records, Volume 9 Page 3663)

-----  
Set Qr. sec. post, from which  
A B.Oak 6" dia., bears S.16°E., 90 lks. dist.  
A W.Oak 3" dia., bears North, 42 lks. dist.

GL0 Dependent Resurvey by Norman D. Price, Under Special  
Instructions dated April 5, 1940 (DCSO records, Volume 27  
Page 11502)

-----  
Point for orig. ¼ sec. cor., determined by reference to the  
record measurements from the original bearing trees.  
At point for corner, Set an iron post 3 ft. long, 1" dia.,  
18" in the ground to bedrock, and in a mound of stone to  
top, for ¼ sec. cor., with brass cap mkd. ¼ S32  
S5

1943 from which  
A W.Oak dead and down, 12" dia., bears North, 42 lks.  
with blaze decayed. (Old BT)  
A B.Oak 16" dia., bears S.27°E., 90 lks. with blazed  
decayd. (Old BT)  
A Fir 15" dia., bears N.83½°E., 24 lks. mkd. ¼ S32 BT.  
(New BT)  
A Fir 13" dia., bears S.22½°E., 19 lks., mkd. ¼ S5 BT.  
(New BT)

Douglas Co. Surveyors Office - Bruce R. Rogers, Deputy; Wm.  
Stoffel; Mike Stone - July 15, 1965 - C.S. File 54/7-1

-----  
Found - Orig. 16" B.Oak S.11°E., 90 lks., now low cut  
stump.  
Orig. 12" W.Oak North 32 lks., now fallen snag.  
15" Fir (1943 resurvey) N.83½°E., 24 lks., now  
stump, scribing visible.  
13" Fir (1943 resurvey) S.22½°E., 19 lks., now  
stump scribing visible.  
New BTs - 11" Oak S.63°W., 23.6 ft. mkd: ¼ S5 CS BT.  
7" Oak N.45°W., 29.6 ft. mkd: ¼ S32 CS BT.

Bureau of Land Management Dependent Resurvey - Wayne Rogers  
et al - Under Group #1386 - Survey June, 1987-Sept. 1988  
(DCSO records, Volume 48 Page 18476)

-----  
Found the ¼ sec. cor. of secs. 5 and 32, monumented with an  
iron post, 1" dia., firmly set, projecting 15" above ground  
with properly marked brass cap. (1943) continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 240700

PRIMARY CORNER DESCRIPTION ¼ Sec Cor for 5; & 32 of T.25-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which bearing tree mkd. by Bruce R. Rogers, Deputy County Surveyor, in 1965  
A W.Oak 10" dia., bears N.44½°W., 45 lks., with healed blaze.  
and a new bearing tree  
A Ponderosa Pine 15" dia., bears S.85°E., 15 lks., mkd. ¼ S5 BT.  
Corner is located on SW. slope.

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike  
- 11/6/2007 - C.S. File 67/24-44  
-----  
Found ok as per BLM renewal of 1987-1988

Douglas Co. Surveyors Office - Crew: Jeff Lorsung- 11/26/2024  
- C.S. File 67/59-17  
-----  
Found - GLO brass cap (properly mkd) in mound of stone.  
15" rotted Fir stump N.83½°E., 15.8 ft.  
13" rotted fir stump S.22½°E., 12.5 ft.  
12" w.Oak N.44½°W., 29.7 ft. (rec. 45 lks)  
20" Ponderosa Pine, S.85°E., 9.9 ft. (rec. 15 lks)  
New tags, spikes, no flagging due to cattle.  
Oregon Coordinate Reference System  
Cottage Grove - Canyonville Zone  
N 186447.456 E 231405.342