

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T27-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 10 Page 4351)

Set post, cor. to secs. 33, 34, 3 & 4, from which
A Pine, 16" dia., bears S.64°E., 55 lks. dist.
A Pine 16" dia., bears N.14°W., 70 lks. dist.
A Red Fir 25" dia., bears N.75°E., 54 lks. dist.
A Red Fir 26" dia., bears S.75°W., 50 lks. dist.

Bureau of Land Management survey by Harold D. Corbing under
Group #350. Survey Aug/Nov. 1958 (DCSO records, Volume 29
Page 12414)

Cor. determined at record distance from the remains of the
original bearing trees:

A Fir stump 42" dia., bears N.78°E., 54 lks. dist. with
a healed blaze. (Rec. bearing N.75°E.)
A stump hole, with roots and bark of a Pine, bears
S.64°E., 55 lks. dist.
A Fir stump 36" dia., bears S.78°W., 50 lks. dist., no
marks visible. (Rec. bearing S.75°W.)
A down and rotted Pine 20" dia., bears N.11°W., 70 lks.
dist., no marks visible. (Rec. bearing N.14°W.)

At the corner point

Set an iron post 28" ling, 2½" dia., 24" in the ground with
brass cap mkd.

T 26 S R 3 W

S 33 | S 34

S 4 | S 3

T 27 S

1958

from which

A Cedar 13" dia., bears N.32¾°E., 47 lks. dist., mkd.
T26S R3W S34 BT.

A Fir 9" dia., bears S.47¼°E., 15 lks. dist., mkd. T27S
R3W S3 BT.

A Fir 10" dia., bears S.68°W., 17 lks. dist., mkd.
T27S R3W S4 BT.

A Fir 11" dia., bears N.45°W., 17 lks. dist., mkd. T26S

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack
Heritage - Feb. 1966 - C.S. File 54/7-57

Found - 1958 Cadastral Brass cap mkd. for section corners.
13" Cedar N.32¾°E., 31.0 ft. scribed T26S R3W S34
BT. Alive.
9" D.Fir S.47¼°E., 9.9 ft., scribe visible on
pitched face.

(Cont. Next Page)

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. 33 & 34; 3 & 4 of T.27-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

10" D.Fir S.68°W., 11.2 ft. pitched & almost healed blaze.
11" D.Fir N.45°W., 11.2 ft., down & dead, scribing visible.
New BT - 9" D.Fir N.18½°W., 35.5 ft. mkd. T26S R3W S33 CS BT. This corner lies approx. 120 ft. east of logging road, course NE and SW in young fir, cedar and laurel.

BLM resurvey by Wayne L. Rogers and Lance J. Bishop, Cadastral Surveyors, under Group #1189, surveyed May/July 1984 - (DCSO records Vol. 47 Page(s) 17961)

The Sec. Cor., monumented with an iron post 2½" dia., firmly set, projecting 6" above ground with brass cap mkd. in 1958 from which the remains of the original bearing trees:
A Fir stump 48" dia., bears N.78°E., 54 lks. dist. with fragmentary scribe marks visible on opened blaze.
A Fir stump 40" dia., bears S.78°W., 50 lks. dist. with healed blaze.
and the remains of bearing trees mkd. by Corbin:
A Cedar 15" dia. bears N.32¾°E., 47 lks. with fragmentary scribe marks visible on partially healed blaze.
A Fir 10" dia., bears S.47¼°E., 15 lks. with healed blaze
A Fir snag 11" dia., bears S.68°W., 17 lks. dist., with healed blaze.
A root hole with down Fir alongside 12" dia., bears N.45°W., 17 lks. dist., with scribe marks T26S R3 S33 visible on partially healed blaze.
and new bearing trees:
A Pine 5" dia., bears S.12°W., 40 lks. dist. mkd. X BT.
A Cedar 13" dia., bears N.88°W., 52½ lks. dist. mkd. T26S R3W S33 BT.

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 1/10/2008 - C.S. File 67/25-6

FD. Ok, 4 live BTs.