

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #55 dated March, 1855
(DCSO Records, Volume 10 Page 4356)

Set post, cor. to secs. 21, 22, 27 and 28, from which
A Laurel 36" dia., bears S.51°E., 200 lks. dist.
A Laurel 30" dia., bears S.5°W., 268 lks. dist.
A W.Oak 17" dia., bears N.20°W., 480 lks. dist.
A B.Oak 12" dia., bears N.5°E., 1009 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy
Milo Godfrey; Clete Putnam - Sept. 15, 1959 - C.S. 49/48-4

Found - Orig. 17" now 26" W.Oak N.20°W., 316.8 ft., down &
partly rotted, previously opened, shows good
scribing "S".
Orig. 12" now 24" B.Oak, now snag, N.5°E., 666.0 ft
I opened, shows good scribing "S22"
Badly burned Laurel snag that checks fair for orig.
SW BT.

Note: I find bearings & distances for orig. BTs do not check
record. This condition is found relative to position of sec.
cor. Corner is 90 ft. East of wire fence.

Set brass cap at corner mkd: S21|S22 T26S R3W 1959
S28|S27 County Surveyors Office

New BTs- 29" Cedar bears N.11°E., 16.7 ft. scribed S22 T26S
R3W CS BT.
15" R.Fir bears N.66°W., 25.3 ft. scribed S21 T26S
R3W CS BT.
7" Cedar bears S.73°W., 10.6 ft. scribed S28 T26S
R3W CS BT.
28" Cedar bears S.82°E., 19.2 ft. scribed S27
T26S R3W CS BT.

BLM resurvey by White, Beck & Reynolds - 1962-63
(DCSO records, Vol. 32 Pages 13381-82) Found 3 orig. BTs &
4 Byron BTs and Byron Brass cap.

BLM resurvey by Berry; Popken; Carlson, 1972 (DCSO records
Volume 37 Page 15404) Found 1 Orig. BT and 4 Byron BTs plus
Byron Brass cap. (Corner is located in barbed wire fence,
extending N.5°W., and S.5°E.