

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #55 dated March, 1855
(DCSO Records, Volume 10 Pages 4357-58)

Set post, cor. to secs. 26, 27, 34 and 35, from which
A Laurel 10" dia., bears S.73°W., 156 lks. dist.
A Laurel 12" dia., bears N.34°W., 175 lks. dist.
A Pine 5" dia., bears N.41°E., 114 lks. dist.
A Pine 15" dia., bears S.33°E., 119 lks. dist.

GLO survey by L.L. Williams & A.R. Flint, Under Contract
#151 dated May 23, 1871 (DCSO records, Vol. 10 Pg 4376)

Reset the old post and put a pile of stones around the same.

Bureau of Land Management resurvey by Popken; Berry; and
Carlson - Under Group #768 - Survey June 1972-April 1975
(DCSO records, Vol. 37 Page 15396)

Point for the cor. of secs. 26, 27, 34 and 35, at
proportionate distance; there is no remaining evidence
of the original corner.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 12
ins. in the ground, in a mound of stone, 3 ft. base, to top,
with brass cap mkd. T 26 S R 3 W
S 27 | S 26
S 34 | S 35
1972

from which
A Cedar 7" dia., bears N.66°E., 59 lks. dist., mkd.
T26S R3W S26 BT.
A Fir 7" dia., bears S.61°E., 50 lks. dist., mkd.
T26S R3W S35 BT.
A Cedar 13" dia., bears S.51°W., 38 lks. dist., mkd.
T26S R3W S34 BT.
A Fir 6" dia., bears N.76°W., 36 lks. dist., mkd.
T26S R3W S27 BT.

From this point, a locally established corner of no record,
bears S.55°48'W., 0.155 chs. dist., monumented with an iron
pipe, ½" dia., firmly set, protruding 8" above ground.

Fd. Brass cap & 4 BTs by D. Bentz, 8/94 - Vol. 18 Pg. 23