TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 and 27

Alias Description
Alias Description
Alias Description
Alias Description

Original - L.L. Williams & A.R. Flint, Under Contract #151 dated May 23, 1871 - (DCSO records, Vol. 10 Pages 4376-77)

Set post to ¼ sec. cor. from which
A Laurel 18" dia., bears N.85°E., 26 lks. dist.
A Laurel 22" dia., bears N.65°W., 40 lks. dist.

Bureau of Land Management resurvey by Berry; Popken and Carlson - Under Group #768 - Survey, June 1972-April 1975 (DCSO Records, Vol. 37 Page 15398)

Point for the ¼ sec. cor. of secs. 26 & 27 at proportionate distance; there is no remaining evidence of the original cor. Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. T 26 S R 3 W

1/4
S 27|S 26
1972

from which
A Cedar 14" dia., bears N.45°E., 37 lks. mkd. ¼ S26 BT.
A Cedar 13" dia., bears S.61°W., 60 lks., mkd. ¼ S27 BT.

Found OK by Ron Geisler, April 1986, C.S. File 63/34-1 (14" Cedar, now stump) - Also June 1986 C.S. 63/34-2

Found OK, Oct. 1995 by Hoffine - M122-80
Cor. Fd. & Used in BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, under Group #1608, surveyed July 1991/April 1995 (DCSO records Vol. 51 page 19302)

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2268, Surveyed July/Nov. 2009 - DCSO records Vol. 57 Page(s) 22702

The ¼ sec. cor. of secs. 26 & 27, monumented with an iron post, 2½" dia., firmly set, projecting 7" above the ground, with brass cap (properly) mkd.
from which the remains of bearing trees mkd. by Berry, Popken, and Carlson in 1972-75
A decayed cedar stump, 15" dia., bears N.45°E., 24.4 ft., with fragmentary scribe marks visible on a partially healed blaze.
A cedar, 22" dia., bears S.61°W., 39.6 ft., with a healed blaze.
and a new bearing tree
A fir, 9" dia., bears S.78¼°E., 26.5 ft., mkd. ¼ S26 BT.
Lat: 43°16'43.62"N. Long: 123°01'47.71"W. (NAD 1983 (CORS))