

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 500660

PRIMARY CORNER DESCRIPTION N 1/16 Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Lester E Calder - For: Weyerhaeuser Co. & Kinnear - Aug. 1943  
- C.S. File 51/87-7  
-----  
Staff compass and abney slope chain survey  
Set post  
50" Fir N.30°W., 31.6'

Survey by Robert Barta Jan. 1965 - reported by Glen  
McChesney - For: Weyerhaeuser- C.S. File 51/306-5  
-----  
Found Calder's BT - 50" fir N.30°W., 31.6' plate only.  
A transit survey was made for Weyerhaeuser Company by R.  
Barta under the supervision of John E. Wilson, Washington  
Lic. Engr..Reg No. 2526, 1/19/-21/65. This survey states:  
"This point set by Calder in 1943 staff compass survey bears  
South 3.63' and East 3.34' from the true calculated N 1/16  
corner in this survey". On 3/11/65 Calder's post and  
reference plate were removed and a 1" aluminum pipe was  
driven for the corner at the true calculated corner position  
according to this transit survey.  
Set - 1" alum pipe set at proportioned distance from  
transit survey.  
New - 12" fir, S.37°E., 15.5 ft. "W" nail & plate.  
18" fir, N.75°W., 40.6 ft. "W" nail & plate.

BLM dependent resurvey by Bryan s. Seibold, Cadastral  
Surveyor & Robert H. Browning, Surveying Technician, under  
Group #1777, surveyed Aug./Sept. 1995 - (DCSO records Vol. 52  
Page(s) 19889-90  
-----  
Point for the N 1/16 sec. cor. of secs. 2 and 3.  
Set a stainless steel post, 28" long, 2½" dia., 27" in the  
ground, with brass cap mkd. N 1/16  
S 3 | S 2  
1995  
from which  
A fir, 8" dia., bears N.13½°E., 10½ lks. mkd. N1/16 S2 BT.  
A fir, 9" dia., bears S.89½°W., 27 lks. mkd. N1/16 S3 BT.  
Deposit a white "DEEP-1" magnetic marker at base of stainless  
steel post.  
The corner is located N., 0.11 chs. of a fence corner,  
extending S. and W.  
From this point, a point established as the N 1/16 sec. cor.  
of secs. 2 and 3 by Robert Barta for Weyerhaeuser Company, in  
1965, bears S.1°32'35"W., 0.048 chs.; monumented with an iron  
pipe, 1½" dia., bent, projecting 2" ins. above ground, from  
which bearing trees mkd. by Barta:  
Continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 500660

PRIMARY CORNER DESCRIPTION N 1/16 Secs. 2 & 3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>A fir, 20" dia., bears S.37¼°E., 24½ lks., no marks visible. A sawed fir stump, 24" dia., bears N.75½°W., 62 lks., no marks visible. This point is rejected due to improper methods and is not utilized in this survey.</p>
<p>Harvey Christensen - For: U.S.R. Company- 4/1998 M128-59 &amp; 10/1999 M 133-77</p> <p>-----</p> <p>Found - 1995 BLM 3.0' Brass Cap, 0.1 ft, above ground BTs - 9" D.Fir, S.89°E., 18.1 ft , scribing visible 9" D.Fir, N.19E., 6.8 ft , scribing visible FD - 1.25' I.Pipe, N.2°38'57"E., 3.21 ft.(Barta) Set - Steel fence post 1 ft east</p>
<p>Douglas Co. Surveyors Office - Crew: Stephen Flause &amp; Jeff Lorsung- 6/20/2023 - C.S. File 67/56-40</p> <p>-----</p> <p>Found - 3" BLM brass cap up 2" 13" burnt, dead D.Fir N.13½°E., 6.9 ft., healed single blaze. 18"x1½ ft. burnt, sawn D.Fir stump S.89½°W., 17.8 ft. evidence of blaze at 9" add 3½" mag nail top center. Corner by Barta for Weyerhaeuser Timber 1½" alum pipe S.1°32'35"W., 3.17 ft. up 4" bent easterly from which: A 24"x2 ft. D.Fir burned and sawn stump S.37¼°E., 16.2 ft., no marks visible.</p> <p>Note - Corner is approx 150 ft westerly of gravel rd. Area burnt 9/2020 Compass decl. 14½°E. Fences reported by BLM now destroyed. Old reprod in NW quadrant. Rest is clear cut on moderate west slope.</p> <p>Oregon Coordinate Reference System Cottage Grove - Canyonville Zone N 185103.814 E 244749.715</p>
<p style="text-align: right;">2</p>