

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Addison R. Flint, Contract #56 dated March, 1855
(DCSO Records, Volume 10 Page 4352)

Set 1/4 sec. post, from which
 A Red Fir 8" dia., bears S.88°E., 15 lks. dist.
 A Red Fir 27" dia., bears N.47°E., 17 lks. dist.

Bureau of Land Management survey by Harold D. Corbin, Under
Group #350 - Survey Aug/Nov. 1958 - (DCSO records, Volume 29
Page 12411)

Point for the 1/4 sec. cor. of secs. 2 and 35, at proportionate
distance; there is no remaining evidence of the original cor.
Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with
brass cap mkd.

T 26 S R 3 W

1/4 $\frac{S\ 35}{S\ 2}$

T 27 S

1958

from which

A Fir 50" dia., bears N.59 1/2°W., 48 lks. dist., mkd.

1/4 S36 BT.

A Fir 30" dia., bears S.2 1/2°W., 116 lks. dist., mkd.

1/4 S2 BT.

Bureau of Land Management survey by Wayne L. Rogers under
Group #1058 - Survey, June/Aug. 1981 (DCSO records, Volume
45 Page 17432)

Found corner monumented with an ironpost, 2 1/2" dia., firmly
set, projecting 8" above ground, with brass cap mkd.

T 26 S R 3 W

1/4 $\frac{S\ 35}{S\ 2}$

T 27 S

1958

from which the remains of bearing trees mkd. by Corbin

A Fir 42" dia., bears S.2 1/2°W., 116 lks. dist.,
with healed blaze.

A sawed Fir stump, 57" dia., bears N.56 1/2°W., 48 lks.
dist., with healed blaze. (Rec. N.59 1/2°W.)

and a new bearing tree

A Fir 6" dia., bears N.2°E., 25 lks. dist., mkd.

1/4 S35 BT.

The corner is located on S. edge of logged area.