

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 26 & 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - L.L. Williams & A.R. Flint, Under Contract #151 dated May 23, 1871 (DCSO records, Vol. 10 4376)

-----  
Set post for 1/4 sec. cor. from which  
A Fir 6" dia., bears N.20°W., 81 lks. dist.  
A Fir 6" dia., bears S.65°E., 150 lks. dist.

Bureau of Land Management resurvey by Popken; Berry and Carlson Under Group #768 Survey June 1972-April 1975 (DCSO records, Vol. 37 Pages 15396-97)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 40 ins. in the ground, with the top 12 ins. below surface of ground with brass cap mkd.  
T 26 S R 3 W  
1/4 S 26  
S 35  
1972

from which  
A Cedar 27" dia., bears N.53°E., 86 lks., mkd 1/4 S26 BT.  
A Cedar 18" dia., bears S.83°E., 31 lks., mkd 1/4 S35 BT.

Mark Smalley - For: Roseburg Resources - 8/ 2003 - C.S. File 65/48-12

-----  
Found - 1972 BLM brass cap (properly mkd)  
26" Cedar N.53°E., 56.8 healed (rec. - 27")  
22" Cedar S.83°E., 20.5 healed.  
New - 13" Fir S.80°W., 34.6, scribed "1/4 S BT"  
12" Pine N.54°W., 24.9, scribed "1/4 S BT"  
Note - Corner is approx. 20" below road surface.

BLM Dependent Resurvey by A Bert Skeesick, Cadastral Surveyor and Robert H Browning, Survey Tech, Under Group No. 2268, Surveyed July/Nov. 2009 - DCSO records Vol. 57 Page(s) 22701

-----  
The 1/4 sec. cor. of secs. 26 and 35, perpetuated by Smalley, in 2003, monumented with an iron post, 2 1/2" dia., firmly set, buried 20". below the ground, with brass cap (properly) mkd. from which the BTs mkd by Berry, Popken, & Carlson in 1972-75  
A cedar, 33" dia., bears N.47 3/4°E., 55.1 ft., with a healed blaze. (Record, N.53°E., 56.8 ft.)  
A cedar, 25" dia., bears S.83°E., 20.5 ft., with a healed blaze.  
and bearing trees mkd. by Smalley  
continued next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A fir, 17" dia., bears S.78°W., 34.8 ft., with a healed blaze.  
A pine, 13" dia., bears N.58¼°W., 25.3 ft., with a healed blaze.  
Corner is located on the E. edge of a dirt road, 15 ft. wide, bears N.35°E. and S.25°W.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 12/1/2021 (Filed 4/11/2022) - C.S. File 67/51-37  
-----

Found - BLM brass cap buried 14" below surface. Properly mkd  
A 30"x30' burnt out cedar shell N.47¼°E., 55.1 ft. with healed blaze. 1975  
27" burnt dead cedar S.83°E., 18.5 ft. (rec. 20.5 ft.) with healed blaze. 1975  
19" Fir S.78°W., 34.2 ft. (rec. 34.8 ft.) with healed blaze. 2003  
14" Pine N.58¼°W., 24.9 ft (rec. 25.3) healed blaze, dist to nail left side center. 2003

New - A 5/8"x15" iron rod with DCS0 yellow plastic cap plumb over fd brass cap, projecting 2" above ground.

Note - Corner is on E edge of a dirt rd. 15' wide bears N.35°E., S.35°W.  
Area burnt 9/2020  
Compass decl. 14½°E.  
See attached sketch.

Lat: 43°16'17.40" N Long: 123°01'11.63" W