

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - L.L. Williams & A.R. Flint, Under Contract #151 dated May 23, 1871 (DCSO records, Vol. 10 Page 4383)

-----  
Set a Cedar post, 4 ft. long, 5" dia., 20" in the ground, for the cor. to secs. 11, 12, 13 and 14, from which  
A Hemlock 20" dia., bears N.42°E., 80 lks. dist.  
A Fir 30" dia., bears S.50°E., 18 lks. dist.  
A Hemlock 8" dia., bears S.38°W., 33 lks. dist.  
A Fir 60" dia., bears N.15°W., 27 lks. dist.

Doug. County Surveyors Office - Milo E. Godfrey, Deputy - Wm. Stoffel; Mike Stone - Sept. 1964 - C.S. File 53/34-1

-----  
Found - 66" Fir N.15°W. 17.8 ft (to face) bark scribing vis Rotten Hemlock stub N.42°E., 52.8 ft., fragments of unmistakable scribing visible.  
45" Fir S.27°E. (Not S.50°E.) 11.9 ft., Old bark face visible, no scribing found.  
No trace of SW BT.

Corner location falls in logging road to be built.

Set Witness Corner 70 ft. West of Corner.

Set Brass cap at Wit. Cor. mkd. County Surveyors T26S R3W WC  
70' E. to Cor. Office, 1964 S11|S12  
S14|S13

New BTs - 23" Red Cedar N.5°E., 35.4 ft. mkd. WC T26S R3W S12 CS BT.  
14" hemlock N.69°W., 49.5 ft. mkd. WC T26S R3W S11 CS BT.  
39" Red Cedar S.51°W., 37.0 ft. mkd. WC T26S R3W S14 CS BT.  
38" Red Cedar S.75°E., 15.0 ft. mkd. WC T26S R3W S13 CS BT.

Doug. County Surveyors Office - Gary L. Langlitz; L.E. Monrean, Frank Silagy - March 15, 1978 - C.S. File 59/46-13

-----  
Found - 1" I.P. approx. 10" above ground, attached cap properly marked. (Wit. Cor.)  
No trace of orig. corner or bearing trees found.  
Corner falls in road.  
A Red Cedar 23" now 25", alive with broken top, bears N.5°E., 35.4 ft. Found scribing on double blaze, "WC T26S R3W S12 CS BT" partially healed.  
A Red Cedar 39" now a 40" windfall, bears S.51°W., approx. 37 ft. Tree scribed "WC T26S R3W S13 CS BT" on double blaze. Cont. next page

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec Cor for 11, 12, 13 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A Red Cedar 38" now 40" broken stump, bears S.75°E., 15.0 ft., scribing visible on partially healed double blaze, "WC T26S R3W S13 CS BT".  
A 14" hemlock found cut and uprooted, has been displaced from original position. Scribing found "CS BT".  
No new monument set.  
New BT - A Red Cedar 12", bears N.88°W., 42.6 ft. Tree scribed "WC S11 CS BT".  
Corner lies approx. 40 ft. SW of road and approx. 40 ft. NW of a draw running NE. Cor. lies in a clear cut area.

Kevin Schinnell - For: Rosboro Lumber Co. - 5/2006 - M150-51  
-----  
Found - 2½" brass monument on ½" iron pipe & 2 accessories as follows:  
28" cedar N.09°E., 34.36'  
15" cedar N.88°W., 42.03'  
New - 14" hemlock S.71°W., 15.48'  
Note - All accessories repainted and flagged at this time. Actual corner position falls in traveled surface of road.

Dependent resurvey by Jeffrey O Covington, cadastral Surveyor under Group 2953, Surveyed Sept/Oct 2019 (DCSO Records Vol. 59 Pages 23986-23988 and Plat maps T26-3 2021-1 thru 2021-3)  
-----  
The cor. of secs. 11, 12, 13, & 14, perpetuated by Godfrey, in 1964; subsequently perpetuated by Douglas County Surveyor's Office, in 1978; and further perpetuated by Schinnell, in 2006; from original evidence no longer in existence; as determined at record bearing and distance from the witness corner established by Godfrey.  
At the corner point  
Set an iron rod, 30" long, 5/8" dia., 38" in the ground, with aluminum cap mkd.  
T26S R3W  
S11|S12  
S14|S13  
2019  
from which new accessories  
A fir, 18" dia., bears N.38¼°E., 48.1 ft., mkd. T26S R3W S12 BT.  
A cedar, 10" dia., bears S.16¼°E., 45.6 ft., mkd. T26S R3W S13 BT.  
An iron rod, 30" long, 5/8" dia., set 29" in the ground, for a reference monument, bears S.11°38'30"W., 38.00 ft., with aluminum cap mkd, RM T26S R3W S14 38.00 FT TO COR and an arrow pointing to the cor. Cont.

PRIMARY CORNER DESCRIPTION Sec Cor for 11, 12, 13 and 14

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

From this cor. a point established as a witness corner for the cor. of secs. 11, 12, 13, and 14 by Godfrey, bears West, 70.00 ft.; and is accepted as a reference monument; monumented with an iron post, 1¼" dia., firmly set, projecting 10" above ground, with a brass cap mkd. COUNTY SURVEYORS OFFICE WC T26S R3W S11 S12 S13 S14 70 FT E. TO COR 1964; from which the remains of the BTs mkd. by Godfrey

A cedar, 32" dia., bears N.3¼°E., 35.2 ft., with a healed blaze.

A cedar snag, 40" dia., bears S.77½°E., 14.5 ft., no marks visible.

A roothole bears S.49°W., 35.3 ft., alongside of which is a down cedar trunk, 40" dia., no marks visible.

and a BT mkd. by Douglas County Surveyor's Office

A cedar, 18" dia., bears West, 42.5 ft., with a healed blaze.

and a bearing tree mkd. by Schinnell

A hemlock, 15" dia., bears S. 69¾°W., 16.0 ft., with no marks visible on partially healed blaze.

At the request of the Douglas County Surveyor, change the marks on the brass cap to now read COUNTY SURVEYORS OFFICE RM T26S R3W S11 S12 S13 S14 70 FT E. TO COR BLM 2019 1964 and an arrow pointing to the cor.

Corner is located S., 3 ft. from the center line of a graveled road, 20 ft wide, bears S.85°E. and N.30°W.

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 5/25/2021 (Filed 11/22/2021) - C.S. File 67/51-6

Found - 2½" dia., brass cap on 1" I.D. iron pipe protruding 12" above ground. DCS0 1964

A 31" R.Cedar, healed blaze; bears N.5°E., 34.8 ft. (Rec. 35.4 ft.) 1964 DCS0

A 18"x24 ft. dead R.Cedar snag, healed blaze; bears N.88°W., 42.6 ft. (as per record) 1978 DCS0

A 14"x6½ ft tall hemlock stump, 6 notches on face no scribing; bears S.71°W. 16.1 ft (rec 15.48') 2006

2019 pending BLM resurvey - \*SEE ABOVE

An 18" D.Fir, blaze scar face burned with some scribing visible; bears N.69¾°E., 106.7 \*(BLM B&D from true corner position N.38¼°E., 48.1 ft.

A fire killed 10" R.Cedar with a burned face: bears S.62¼°E., 93.8 ft. \*(BLM B&D from true corner position S.16¼°E., 45.4 ft)

Note - WC is West 70.0 ft from True corner position  
Lat: 43°18'55.62" Long: 123°00'43.10 W  
Compass decl. 14½°E.