

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W. H. Byars, Contract #317, dated Jan. 20, 1879
(DCSO records, Vol. 10 Page 4383)

Set Chinquapin post, 5 ft. long, 6" dia., 24" in the
ground, for the 1/4 sec. cor. bet. secs. 11 and 12, from which
A Chinquapin 10" dia., bears N.60°E., 17 lks. dist.
A Fir 36" dia., bears S.10°W., 10 lks. dist.

Ben B. Irving - M.L. Kimmel; Fred Schmidt; N.E. Richardson
Feb. 6, 1933 - C.S. File 37/155

Location identified from O.B.T., 36" Fir, S.10°W., 10 lks.
Set a Fir post 4 x 4 x 42" from which
A Fir 18" dia., bears S.28°E., 45 lks. mkd. 1/4 S13 CSBT.
A Cedar 15" dia., bears S.44°W., 85 lks. mkd. 1/4 S11 CSBT.
(Old typed renewal called this a Fir, which was a
typo error).

CORNER REPORT ONLY - Doug. County Surveyors Office - R.B.
Kimberling; M. W. Cline - Sept. 28, 1977 - C.S. File 59/40-26

Found - 1 1/2" alum. alloy pipe 12" above ground.
36" now 26" fir snag, badly rotted, bears S.15°W.,
7.6 ft. (OBT rec. S.10°W., 6.6 ft.)
15" now 20" Cedar bears S.59°W., (Rec. S.44°W.)
56.1 ft. Found partly healed blaze & scribing
"S11 CS".
12" now 30" S.Pine bears N.59°W., 53.5 ft. with a
well healed blaze.
5" now 8" Yew bears S.16°E., 29.7 ft. with a well
healed blaze.
(Pine and Yew marked by Hale in 1946) (Record source unknown,
probably Weyerhaeuser.)

Doug. County Surveyors Office - Randall Smith; Stephen Flause
May 18, 1988 - C.S. File 62/52-6

Found - A 2" O.D. alum. pipe protruding 12" above ground.
Source unknown.
A position at record (S.44°W., 56.1 ft.) was
occupied from 23" Cedar BT, no other evidence
36" now approx. 38" dia., 3 1/2 ft. high rotted D.Fir
stump, no blazes or scribing found, bears
S.15°W., 7.6 ft. (agrees w/rec. per 1977
report) (Orig. rec. S.10°W., 6.6 ft.; dist. is
a possible face measurement) Possible Orig BT.

Continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

15" now 23" dia. Cedar with a partially healed upper and fully healed lower blaze, scribing visible in upper blaze "S11CS" bears S.59°W., 56.1 ft. (agrees w/1977 record) (Rec. per 1933 Irving, 15" Fir S.44°W., 56.1 ft.) (Tree species is a Cedar in Irving's field book)

18" dia. Fir is gone, possible stump hole found bearing S.41½°E., 29.7 ft. (Rec. per Irving is S.28°E., 29.7 ft.)

Note: Bearings on BTs by Irving, are North of their record position by approx. the same angle.

12" now 36" dia. S.Pine with an axe bark blaze "N/" and a small healed lower blaze, bears N.59°W., 54.8 ft. (Rec. N.59°W., 53.5 ft. is a possible face measurement, source unknown)

5" now 8" dia., Yew with a partially healed double blaze, upper blaze opened, no scribing found. Lower blaze has a Weyerhaeuser W nail set in it, bears S.16°E., 29.7 ft. (agrees with record, source unknown).

Last 2 trees noted as source unknown are possible BTs by Marion D. Hale, date 1946, see C.S. File 53/115.

New BTs - 9" D.Fir double blazed and scribed "¼ S11 CS BT" bears S.36°W., 17.5 ft.

8" D.Fir double blazed and scribed "¼ S12 CS BT" bears N.59½°E., 19.5 ft.

FD. Ok, 4 live BTs as per 1998 renewal, DCS0 2/26/2008, J. Pike & S. Flause, C.S. File 67/25-20

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 6/7/2021 (Filed 11/22/2021) - C.S. File 67/51-9

Found - 2" O.D. alum pipe protruding 15" above ground (source unknown)

Large root hole S.15°W., 7.6 ft.

28" Cedar (burnt dead snag) S.59°W., 57.1 ft. (rec. 56.1) 1977

Root hole N.59°W., 54.8 ft.

6" Yew (Burnt stub) S.16°E., 29.7 ft. 1977

20" D.Fir S.36°W., 17.1 ft. (Rec. 17.5) healed double blaze

11" D.Fir (20' tall burnt snag) N.59½°E., 19.2 ft. (rec. 19.5 ft.) healed double blaze. 1988

New - Added 4" MAG NAILS right side center root crown to 28" Cedar - 20" D.Fir & 11" D.Fir

90" Hemlock (burnt dead) N.70°W., 17.2 ft. to 4" MAG NAIL right side center root crown. Cont. Next pg

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 12

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Note - Area badly burnt 9/2020

Compass decl. $14\frac{3}{4}^{\circ}$ E.

Lat: $43^{\circ}19'21.23$ N Long: $123^{\circ}00'41.03$ " W