

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Section 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Doug. County Surveyors Office - Gary Langlitz; L.E. Monrean  
Stephen Flause - March 9, 1978 - M 65-73; C.S. File 60/7

Found - A partially rotten squared wooden post, (see C.S. File 53/115) bears S.58°W., 1.7 ft. from the center as established in this renewal.)  
From the found wooden post, a 30" Red Cedar bears N.16°W., 3.3 ft. with Weyerhaeuser tag.  
A 40" D.Fir now a windfall bears S.15½°E., 16.4 ft. with Weyerhaeuser tag. (Note: our distance measurements extend to the center of these trees)

Set - Corner location determined by survey. At the cor. point, WE SET a 1" x 30" I.P. 28" in the ground with brass cap mkd: Douglas County Surveyor  
T 26 S  
C 1/4 \_\_\_\_\_ S 12  
R 3 W  
1978

New BTs - 30" Red Cedar scribed "C 1/4 S 12 CS BT" on a double blaze, bears N.35½°W., 3.4 ft.  
6" Grand Fir scribed "C 1/4 S 12 CS BT" on a double blaze bears N.48°E., 9.4 ft.

Corner located at NE corner of recent clearcut unit.

Fd. ok . 2 live BTs as per rec. - DCSO, John Pike & Stephen Flause - 3/3/2008 - C.S. File 67/25-29