

PRIMARY CORNER DESCRIPTION Angle Point #18, Sec. 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM survey by Daniel Berry, Under Group #796, Survey Sept. 1972 (DSCO records, Volume 39 Page 15931)

-----  
Point for angle point No. 18, 100 ft. normal dist. from the left bank of the North Umpqua River.  
Set an iron post, 28" long, 2½" dia., 25" in the ground, and in a mound of stone, 2 ft. base, to top, with brass cap mkd:

\                    \ AP 18  
T 26 S R 3 W    \  
                  S 9  
                  1972

from which  
A Fir 15" dia., bears N.20°E., 53 lks. dist., mkd.  
AP18 S9 BT.  
A Fir 20" dia., bears N.11°W., 96 lks. dist., mkd.  
AP18 S9 BT.

Doug. County Surveyors Office - Larry Monrean, deputy, Randy Smith - Jan. 25, 1985 - C.S. File 62/25-5

-----  
Found - Did not find 1972 BLM brass cap. The location of the corner & one of the BTs fall in a slide area.  
We establish a temporary point from undisturbed BT as follows:  
A 20" dia. Fir with well healed blaze and BT tag bears N.11°W., 63.4 ft. This tree appears to be undisturbed.  
A 15" now 18" Fir with a well healed single blaze is dislodged by slide activity, bears N.23½°E., 49.5 ft. (Rec. N.20°E., 35 ft.) Tree is still standing but leaning.  
New BT - 17" Fir double blazed and scribed "AP 18 S9 CS BT" bears N.85½°E., 115.0 ft.