

PRIMARY CORNER DESCRIPTION Sec. Cor. for 34 & 35; 3 & 2 of T27-4

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855
 (DCSO Records, Volume 11 Page 4428)

 Set post cor. to secs. 34, 35, 2 and 3, from which
 A mound was thrown up as per instructions, no trees near.

Bureau of Land Management Dependent Resurvey - Glenn S.
 Baughman, Contract #52500-CT5-1116, Survey Oct/Dec. 1975
 (DCSO records, Volume 39 Page 15786)

 Point for corner at proportionate distance, there is no
 remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia. 22" in the ground, with

brass cap mkd: T26 S R
 S 34 | S 35 4
 S 3 | S 2 W
 T27S

- 1975 from which
- An Oak 12" dia. bears N.18°E., 60 lks. dist. mkd. T26S
R4W S35 BT.
 - An Oak 24" dia. bears S.23°E., 23 lks. dist. mkd. T27S
R4W S2 BT.
 - An Oak 14" dia. bears S.76°W., 56 lks. dist. mkd. T27S
R4W S3 BT.
 - An Oak 14" dia. bears N.82°W., 62 lks. dist. mkd. T26S
R4W S34 BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
 Stephen J. Flause - 9/26/2000 - C.S. File 66/16-45

- Found - 1975 BLM brass cap/iron pipe, protrudes 8" above
 ground.
 12" now down 13" rotted Oak with a partially healed
 blaze scribing visible "T26S R4W S35 B" root
 hole bears N.18°E., 29.6 ft. (1975)
 14" now 14" down burnt Oak, no scribing visible,
 root hole bears N.82°W., 40.9 ft.
 14" now 16" dia., W.Oak with a partially healed
 rotted blaze I rescribe on a single blaze above
 old blaze "X S3 CS BT" bears S.76°W., 37.0 ft.
 (1975)
 24" now 29" dia., W.Oak with a fully healed single
 blaze bears S.23°E., 15.2 ft. (1975)
- New - 10" W.Oak, double blazed & scribed "T26S R4W S34 CS
 BT" bears N.72°W., 37.2 ft.
 27" B.Oak double blazed & scribed "T26S R4W S34 CS
 BT" bears N.4 1/2°W., 32.5 ft.