TOWNSHIP 26 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 11 Page 4435)

Set ¼ sec. post, from which
A B.Oak 15" dia. bears S.1°E., 232 lks. dist.
A W.Oak 12" dia. bears N.83°W., 278 lks. dist.

J. W. Cole, Co. Surveyor - For: Oak Creek Road Petition Feb. 1923 - C.S. File 8/10

Renewed corner from which original BT bearing rotted out scars, scribe marks faintly visible bears S.1°E., 153.1 ft.
Hole where a tree has stood N.83°W., 183 ft.
Set a binder shaft 1" x 46" and mound of rock.
Marked new trees:
W.Oak 7" dia. bears S.34¾°W., 163.3 ft.
W.Oak 16" dia. bears S.34°E., 72.6 ft.

Doug. Co. Surveyors Office - John Powell; W. Penley; J. Heritage - Jan. 1971 - C.S. File 56/1-2

Found - No trace of 1" binder or mound of rocks, as corner falls in middle of cultivated pasture.
16" now 24" W.Oak S.34°E., 72.6 ft. opened for scribing "S".
Set brass cap in fence line mkd: County Surveyors Office 1971 T26S R4W W.C. 47' N. to ¼ S 34|S 35
New BTs - 8" W.Oak S.5°W., 40.4 ft. scribed "W C ¼ S34 CS BT.
8" W.Oak S.41°E., 25.5 ft. scribed WC ¼ S 5 CS BT.
This Witness Corner lies in E-W pasture fence.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 9/28/2000 - C.S. File 66/16-47

Found - 1971 DCSO brass cap, iron pipe protruding 8" above ground in E-W fence line.
8" now 13" W.Oak with a fully healed double blaze bears S.41°E., 25.5 ft. (1971)
8" now 10" W.Oak with a fully healed double blaze bears S.5°W., 40.4 ft. (1971)
1923 16" now 34" dia., W.Oak with a healed blaze bears S.73¼°E., 44.0 ft. (calculated rec. S.72°E., 42.7 ft) This tree marked in 1923 to face corner, now used to reference 1971 DCSO BC/IP WC.