

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 200400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 17, 18, 19 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to Secs. 17, 18, 19 & 20, from which
A Y.Oak 15" dia. bears N.58°36'E., 1535 lks.
A W.Oak 24" dia. bears S.81°30'W., 639 lks.
A W.Oak 12" dia. bears N.88°26'W., 930 lks.
No tree near in Section 30.

Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone - Jan. & Feb., 1964 - C.S. File 49/125-38

Found - 48" B.Oak N.58½°E., 1013.1 ft. shows very good scar. Tree alive & in good condition.
Down & badly rotted Oak S.81½°W., 421.7 ft. both upper & lower scars opened many years ago, center completely rotted away.
Oak N.88½°W., 613.8 ft. down many years, trunk almost completely buried in swamp, impossible to tell exact spot where it stood.
Set - Brass cap at cor. mkd. County Surveyor's Office, 1964
T26S R5W S 18 | S17
S 19 | S20
New BTs - 12" W.Oak N.87°W., 226.0 ft. mkd. T26S R5W S18 CSBT.
14" W.Oak S.80°W., 316.2 ft. mkd. T26S R5W S19 CSBT.
8" W.Oak N.17½°E., 448.7 ft. mkd. T26S R5W S17 CSBT.
No trees near to S.E.
Note - Fence corner, fences north, west, & SE, bears S5°E 6.0'