

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
A Y.Oak 12" dia. bears West 9 lks.
A Y.Oak 15" dia. bears N.10°E., 36 lks.

J.W. Cole, Deputy Co. Surveyor, May & June 1921, Vol. 3 Pag.93

Set Oak Post, also an Iron RR spike from which the original
BT bears N.10°E., 23.8 ft. bearing scribe marks.
Marked new BTs as follows:
A B.Oak 18" dia. S.40°30'W., 35 ft.
A B.Oak 14" dia. N.73°00'W., 24.2 ft.

Milo E. Godfrey, Deputy Co. Surveyor- Wm. Stoffel; Mike Stone
Jan. & Feb., 1964 - C.S. File 49/125-36

Found - Square Spike buried under loose fill.
Did not find Oak stake.
B.Oak N.10°E., 23.8 ft. previously opened, center
rotted away.
B.Oak N.73°W., 24.2 ft. Has face rotted, no
scribing.
B.Oak S.40½°W. 35.0 ft center completely burned out
Set - Brass cap at Cor. mkd. County Surveyors Office, 1964
T26S R5W ¼ S18|S 17 Set spike alongside.
New BTs - 11" W.Oak S.52°E., 47.5 ft. mkd. ¼ S17 CS BT.
18" B.Oak S.67°W., 54.6 ft. mkd. ¼ S18 CS BT.
Corner is 1.5 ft. West of North & South fence line.

Douglas Co. Surveyors Office - John Pike - Pat Crawford -
9/8/2004 - C.S. File 67/6-20

Found - 1964 BC/IP bent over & buried due to construction of
fire break road.
Square spike (1921) fd. next to BC/IP
B.Oak, now 18" bears N.74°W., 25.5 ft. (1921 & 1964)
Face grown over. (Rec. 24.2 ft.)
B.Oak, now 20" bears S.76½°W., 54.6 ft. (1964) Shows
well defined double blaze. (Rec. S.67°W.)
B.Oak, now 26" bears S.41°W., 37.9 ft. (1921) Burned
out center, still alive.
W.Oak, now 14" bears S.45½°E., 47.5 ft. (1964) Shows
faint double blaze. (Rec. S.52°E.)
Reset - Dug down to point where pipe went straight down.
Then referenced that point & removed bent BC/IP
continued next page

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set - New BC/IP at referenced position. (2" brass cap on
24" IP) mkd: DOUGLAS CO. SURVEYORS
¼ S 18 | S 17
RESET
2004
OFFICE

New - Nearby survey marker DO NOT DISTURB sign bears North
2.0 ft.

Note - Lies on South facing slope approx. 1.5 ft. West of
intermittent N-S fence line on East edge of newly
constructed fire break road.
Comp. declination 17½°E.