

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Original - Elder & Gile, Contract #31 dated April, 1853 ----- Set ¼ sec. post, from which A Pine, 36" dia. bears S.13½°W., 513 lks. A Y.Oak 12" dia. bears N.52½°W., 275 lks.</p>
<p>Fleser - For Taylor - Oct. 28, 1914 - F.B. 36 Page 23 ----- Set - 4" Oak post and mkd. the following trees: Laurel 8" N.60½°W., 19.2 ft. A Fir 20" N.83°E., 18.3 ft.</p>
<p>N.E. Richardson - Oct. 29, 1946 - C.S. File 39/54 ----- Found - Old bearing trees: Remarked Fir in bark N.83°E., 18.3 ft. Set - 1¼" x 30¼" Iron pipe. New BT - 10" Fir S.42½°W., 23.4 ft.</p>
<p>Milo E. Godfrey, Deputy Co. Surveyor - Wm. Stoffel; Mike Stone - Nov.-Dec. 1963 - C.S. File 49/125-15 & RM1-42 ----- Found - 1¼" I.P. set at corner by Richardson, 1946. The Fir tree N.83°E., 18.3 ft. Is now a stump, old face burned. The 10" Fir S.42½°W., 23.4 ft. is now a dead snag, very plain axe scars. The 8" Laurel N.60½°W., 19.2 ft. is still alive & standing. Good scar visible where it was opened in 1946 - face probably rotted. (Flesers BT) New BTs - 14" D.Fir N.64½°W., 17.4 ft. scribed ¼ S20 CS BT. 9" D.Fir S.41½°E., 21.8 ft. scribed ¼ S29 CS BT. Note - Corner is approx. 6" west of N-S fence line.</p>
<p>Douglas Co. Surveyors Office - Randall Smith; Stephen Flause; Terrie Franssen - July 24, 1990 - C.S. 64/10-5 ----- Found - A 1¼" I.D. Iron pipe, firmly set protrudes 3" above ground. (Richardson, 1946) 8" now 12" dia. Madrone with a healed blaze, bears N.60½°W., 18.4 ft. (Rec. N.60½°W., 19.2 ft. dist. is to center of trunk blaze height) 20" now 30" dia. 2½ ft. high rotted D.Fir stump with partial illegible scribing visible on an open blaze, bears N.86°E., 19.1 ft. (Rec. N.83°E., 18.3 ft. dist. is to blaze) (cont. next page)</p>

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

10" now 11" dia. 14 ft. tall D.Fir snag with a partially healed rotted, double blaze, illegible scribing is visible, bears S.42½°W., 23.4 ft.
14" now 21" dia. D.Fir with a fully healed double blaze bears N.62°W., 17.4 ft.
9" now 18" D.Fir with a fully healed double blaze bears S.41½°E., 21.8 ft.
New BTs- 15" dia. Madrone, double blazed & scribed ¼ S20 CS BT bears N.71½°E., 12.6 ft.
18" dia. Madrone double blazed & scribed "¼ S29 CS BT bears S.23½°W., 38.2 ft.
Corner lies in a North-South fence line.