

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 400336

PRIMARY CORNER DESCRIPTION Wit. Cor. to ¼ Cor. Secs. 21 & 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder & Gile, Contract #31 dated April, 1853

-----  
(At 36.50 chains, top of steep and impassable bluff)  
Set Wit. post to ¼ Sec. cor. (inaccessible) from which  
    A Y. Oak 8" dia. bears S.25°E., 113 lks.  
    A Y. Oak 6" dia. bears S.18½°W., 201 lks.

Edwin S. Woodford - Wit. M.E. Godfrey - August, 1952  
C.S. File 41/114-1

-----  
Found both old BTs:  
    8" Y.Oak, S.25°E., 113 lks. (now 24").  
    6" Y.Oak, S.18½°W., 201 lks. (now 20").  
Chopped out southeast tree and found scribe marks in good  
condition - wood still alive and sound.  
Set iron stake for corner.  
Marked 2 new trees for corner:  
    18" D.Fir S.34°30'E., 53.1 ft. scribe ¼ S W C 622 BT.  
    8" B.Oak S.45°W., 59.9 ft. scribe ¼ S W. C. 622 B.T.

Wm. A. Eimstad - June Cape & Doug. Short  
Sept. 1966 - M 32 - 30

-----  
Found ¾" Pine with flat head. Bearing trees in evidence.

Douglas Co. Surveyors Office - Randall Smith & Stephen Flauser  
- Nov. 11, 1997 - C.S. 64/78-27

-----  
No monument fd.  
Bt's Fd.- 8" now broken rotted Oak stub showing evidence of  
being opened no scribing found, bears  
    S.25°E., 75.6' (agrees with rec.) OBT.  
6" now broken rotted Oak tipped out of ground no  
evidence of blazes or scribing found, bears  
    S.18½°W., 132.7' (agrees with rec.) OBT.  
18" now 31" dia. D.Fir, with a fully healed single  
blaze, bears S.34½°E., 53.1' (agrees with  
rec.) 1952.  
8" now 14" dia. B.Oak, with a fully healed single  
blaze, bears S.45°W., 62' (rec. S.45°W.,  
59.9') 1952.

(Cont. next page)

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 400336

PRIMARY CORNER DESCRIPTION Wit. Cor. to ¼ Cor. Secs. 21 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mon. Set- 8" nail in rock bluff, set flush.  
Note: unable to set standard survey monument as corner falls on top of rock bluff.

New Accessories -  
11" dia. D.Fir double blazed and scribed "WC ¼ S22 CS BT", bears S.71½°E., 83'.  
8" dia. D.Fir double blazed and scribed "WC ¼ S21 CS BT", bears S.12½°W., 63.5'.  
Center of knoll at top of gravel pit bears N.5°E.  
Corner lies on top of rock bluff near northerly edge.

Fd. Ok by K. DeGroot, 10/2003 - 2004-0081 A-C