

TOWNSHIP 26 RANGE 05 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Corner for secs 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder & Gile, contract #31 dated April, 1853  
-----

Set ¼ Sec. post, from which  
    A Y.Oak 14" dia. bears S.2½°W., 601 lks.  
    A Y.Oak 12" dia. bears N.51½°E., 147 lks.

County Surveyor's Office, April 15, 1957 - C.S. File 47/174  
-----

Found both old BTs. The tree to the northeast is alive but badly rotted in the center but found scribe marks plain in rotted area.

Set corner at intersection of distances. Read bearings to both trees from this point. The bearing to the northeast tree fits good. The bearing to the tree to the south is S.2½°E., instead of S.2½°W., as called for in gov't notes.

Set - An iron pipe with brass cap marked:

County Surveyor's  
T26S R5W  
¼ 11|12  
1957  
Office.

Marked two new trees:

8" B.Oak N.45½°W., 67.8 ft. mkd. ¼ S 11 CS BT.  
24" B.Oak N.49°E., 109.7 ft. mkd. ¼ S 12 CS BT.

Douglas Co. Surveyors Office - Milo Godfrey & crew - 2/5/1964  
(added 6/30/2022) - C.S. File 49/125-31  
-----

BTs mkd in 1957 still in good condition.