

PRIMARY CORNER DESCRIPTION NW Cor. Hannan DLC #42

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Contract #28 dated April, 1854

-----  
Set post, from which

A W.Oak 18" dia. bears S.8°E., 71 lks.

A W.Oak 20" dia. bears S.85°E., 76 lks.

-----  
J.W. Cole, Deputy - May 1921 - F.B. 51 Pg.17, M 1-69

I renewed this corner my measurement from corner 13.30 chains South. I set 4 x 4 x 40" post, also an Iron pipe 1½" x 30" dia. from which:

A B.Oak 20" dia. bears N.43°E., 33.8 ft.

A B.Oak 14" dia. bears S.40°E., 62.0 ft.

-----  
James W. Byron, Deputy Co. Surveyor - March 9-22, 1956  
C.S. File 47/67

-----  
Found - ¾" I.P. set by Cole. This I.P. checks Cole's and orig. record distance from the West SW cor. of DLC 42. Also agrees with Lot and gov't corners that I tied in North of this point.

Set - I set an iron pipe with brass cap alongside of Cole's ¾" I.P. & mkd. N.W. corner Cl 42 T26S R6W County Surveyors Office 1956.

Blaze & scribe:

6" W.Oak bears S.36°E., 37.8 ft. scribed N W Cl 42 CS BT.

24" B.Oak bears S.24°W., 75.7 ft. scribed T26S R6W N W Cl 42 CS BT.

-----  
Milo E Godfrey, Deputy-Mike Stone-June 1964 - C.S. File 52/87-44

-----  
Found - B.Oak (now dia.) S.24°W., 75.7 ft. Portion of scribing visible in now completely healed scar. SE BT mkd. in 1956 bulldozed into large brush pile. No evidence found of where it had stood. Did not find pipe set by Cole, nor our brass cap set in 1956.

Set - New I.P. with brass cap mkd: "County Surveyors Office 1964 T26S R6W N.W. D.L.C. 42| ."

Did not find either of Cole's BTs nor either orig. BT.

continued next page

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 042020

PRIMARY CORNER DESCRIPTION NW Cor. Hannan DLC #42

Alias	Description
Alias	Description
Alias	Description
Alias	Description

New BT - 20" B.Oak S.15°E., 30.5 ft. mkd. "NW DLC 42 CS BT".  
A N. & S. fence line is 40 ft. west of corner  
(distance paced)

Douglas Co. Surveyors Office - Karen Reed; P.L. Earle  
April 18, 1979 - C.S. 60/24-24

-----  
Found - A 1" x 36" I.P. with brass cap, properly mkd.,  
          leaning against SE BT.  
          I do not find 1954 brass or a 1½ I.P.  
          A 24" B.Oak now 26" bears S.24°W., 75.7 ft. with  
          well healed double blaze.  
          A 20" B.Oak bears S.15°E., 30.5 ft. with well  
          healed double blaze.  
          A N-S fence bears West 39.0 ft.(Rec. 40.0 ft.)  
Set - 5/8" x 30" I. Rod with alum. cap mkd. "Douglas  
          County Surveyor" NW DLC 42 1979" at proper  
          bearings & distance from found BTs. Buried  
          6" below surface.  
          A 1" x 36" I.P. with brass cap mkd. "County  
          Surveyors Office" T26S R6W WC East 30 ft.  
          NW DLC 42 1979, set west, 30.0 ft. from I.Rod.  
BT - 20" B.Oak bears S.54°E., 48.8 ft. from wit. cor.  
Corner falls in gravel drive.  
(Sketch attached to field notes in C.S. File)

Fd. OK by D.Edwards, Aug. 1998 - 1998-0091

Fd. OK by M. Heimbunger, Aug. 2003 - M142-77