

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 31; and 36 of T.26-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
 A Yellow Oak 15" dia. bears N.58½°E., 84 lks.
 A W. Oak 18" dia. bears N.45½°W., 310 lks.

William B. Paulin, Doug. Co. Road Dept. (date ?)
C.S. File 58/176-42

Found large rotten Oak hollow in center. Found remnants of upper & lower blazes. Could not find visible scribe. Found evidence of axe mark along edge of one face. Went into other quadrant record distance & bearing. Found old stump cut off short but showing remains of lower half of blaze. Assume first mentioned tree to be original BT.

Don E. Garrett, For: Willard Nickolaus - Dec. 29, 1967
M 35-17

1/4 Corner set from field notes by William Paulin -
Set 5/8" iron rod at 1/4 Corner.
Set - Brass cap stamped W.C. 1/4 S 36 T26S R7W S31 T26S
 R6W LS 544 30 ft. West to Cor.
 16" Oak bears S.16°W., 16.3 ft. scribed WC ¼ S31 BT.

Douglas Co. Surveyors Office - Randall Smith; Stephen Flauser
January 5, 1990 - C.S. 64/5-1

Found - 1967 2¼" dia. brass cap on a 1¼" O.D. Iron pipe that protrudes 4" above ground.
5/8" Iron rod set at a position for ¼ corner is under AC in road. A strong metal reading was taken at a point 30 ft. West of witness cor.
16" now 19" dia. W. Oak with fully healed double blaze bears S.16°W., 16.3 ft.
5/8" Iron rod property pin bears West, 1.19 ft. (See M 35-17)
5/8" Iron rod property pin bears N.1½°W., 59.87 ft. (Rec. N.1°08'09"W., 60.01 ft. M 35-17)

(Cont Next Page)

