

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32, T25-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set post cor. to secs. 31 32, 5 and 6, from which
A Y.Oak 16" dia. bears S.20°W., 49 lks. dist.
A W.Oak 18" dia. bears N.63W., 67 lks. dist.
Made trench, no other trees being near.

C.E. Roberts, Nov. 3, 1908 - Field Book 7 Pg. 76

Reset SE cor Sec. 31, Sandstone 8x8x16" mkd C.S.
Witness trees cut down, markings still legible.

James W. Byron, Deputy Co. Surveyor - Milo Godfrey; Clete Putnam - Dec. 8, 1959 - C.S. File 52/5 - M 16-59

Found - Stone as recorded CS chiseled on North face.
3/4" I. Rod alongside stone.
New BTs - 4" W.Oak bears S.72°E., 11.1 ft. scribed S5 CSBT
10" B.Oak bears N.7°E., 61.3 ft. scribed S32 T25S
R6W CS BT.
10" Laurel bears S.79°W., 46.6 ft. scribed S 6
T26S R6W CS BT.
6" Laurel bears N.36°W., 38.8 ft. scribed S31 CSBT.

Doug. Co. Surveyors Office - S.J. Flause; Karen Reed
March 15, 1979 - C.S. File 60/24-19

Found - 9"x9"x17" Rock mkd. "CS" on north face.
5/8" I.Rod set next to rock. (unrecorded)
A root hole bears S.20°W., 32 ft. (orig.)
A 4" Oak bears S.72°E., 11.1 ft., tree down &
rotted.
A 10" B.Oak now 14" bears N.7°E., 61.3 ft. with well
healed double blaze.
A 10" Madrone now 14" was removed by cat work, has
tag and shows good scar.
A 6" Madrone now 10" trunk on triple trunk tree
bears N.38°W., (Rec. N.36°W) 38.8 ft. to face
39.8 ft. to center of base with well healed
double blaze.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32 of T25-6

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

	<p>Set - 1" x 36" I.P. with brass cap mkd. "Douglas County Surveyor" T25S S31 S32 S6 S5 T26S R6W 1979. Cap 5" above ground, rod 9" above ground. Cap in position of stone. Placed stone next to cap and rod east side of cap.</p> <p>New BTs - 12" Madrone bears S.31°E., 50.4 ft. scribed "S5 T26S R6W CS BT". 11" Oak bears S.33°W., 158.5 ft. scribed "S6 T26S R6W CS BT".</p>
	<p>Douglas Co. Surveyors Office - Randall Smith; Stephen Flauser Jan. 31, 1990 - C.S. File 64/5-10</p> <p>-----</p> <p>Found - A 2½" dia. 1979 DCSO brass cap on a 1¼" O.D. I.P. protrudes 6" out of ground, now bent approx. 12" north of plumb. 5/8" dia. I.Rod protrudes 9" out of ground, now bent approx. 15" north of plumb. I.R. found along north side of DCSO BC/IP. 9"x9"x17" stone no marks visible found approx. 2 ft. north of DCSO BC/IP's plumb position. (Bearings & distances taken to plumb position of DCSO BC/IP.) 10" now 14" B.Oak with a fully healed double blaze bears N.8½°E., 59.9 ft. (Rec. N.7°E., 61.3 ft. slope distance) 6" now 14" Madrone with fully healed blazes bears N.36°W., 38.8 ft. (per record) 12" now 14" Madrone with partially healed double blaze scribing visible "T26S R6W" bears S.31°E., 50.4 ft. 11" now 14" Oak with fully healed double blaze bears S.34½°W., 158.5 ft. (Rec. S.33°W., 158.5 ft.)</p> <p>Set - Position of bent DCSO BC/IP is referenced. DCSO BC/IP is straightened & returned to referenced position. BC/IP now protrudes 3" above ground. 5/8" I.R. is straightened & set along North side of Brass cap. 5/8" I.R. now protrudes 1" above ground. Stone is placed along East side of DCSO BC/IP. BC/IP measures 36". 5/8" I.R. measures 50" long.</p> <p>Corner lies on a NW-SE running ridge on a bench approx. 50 ft. North of a dirt road.</p>
	<p>Found OK by C. Sweeden, Aug. 2001 - M138-58 Found OK by D. Edwards, June 2003 - M142-50</p>
	<p>continued next page</p>

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 200700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5 & 6; 31 & 32 of T25-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

DCS0-GIS Corner visitation - 6/21/2004 - Typed: 1/25/2011 -
C.S. File 67/33-1

Monument - BC/IP 1.25"
Comment - OK

Fd BC by D.Edwards, 5/2014 - M168-39

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and
Jeff Lorsung - 1/9/2025 - C.S. File 67/59-43

Found - 1" I.D. Iron pipe badly bent. Brass cap missing.
19" B.Oak N.8½°E. 59.9' healed double blaze.
20" Madrone N.36°W. 38.8' healed blazes.
15" Rotted base madrone 6" & 8" sprouts. S.31°E.
50.4' healed double blaze.
21" Oak S.34½°W. 158.5' healed double blaze.
⅝" I. Rod on N. edge of mon. Orig corner stone on
E. edge of monument.

Set - Reference pipe location set 2¼" alum pipe with 3¼"
alum cap at referenced location flush with ground
Stamped: DOUGLAS COUNTY T25S R6W S31, S32, S6,
S5 T26S R6W 2025 RESET SURVEYORS OFFICE

NOTES - Mon is approx 50' north of gravel driveway.
Compass decl. 14½°E.