

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 400340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder & Gile, Contract #31 dated April, 1853

Set ¼ sec. post, from which
 A Y.Oak 24" dia. bears S.40¼°E., 197 lks.
 A Y.Oak 30" dia. bears S.66½°W., 133 lks.

J. W. Cole, Deputy Co. Surveyor - May 1921
F.B. 50 Pg. 66 & M 1-69

I renewed this corner from the rotted remains of both original trees which check closely for direction & distance. I set an Oak post 4 x 4 x 40", also an Iron pipe 1" x 30" from which mark new trees:
 A B.Oak 10" dia. bears S.54°W., 6.4 ft.
 A B.Oak 10" dia. bears N.30¼°W., 16 ft.

James W. Byron, Deputy - M. Godfrey; S.A. Bilow
October 28, 1958 - C.S. file 49/121-2

Found - 1" Iron pipe at corner & rotted scribed stake near. Cole's BTs, now partly rotted stumps, both show good scribe marks.
I do not set brass cap at corner.
New BTs- 20" B.Oak bears N.9°W., 542.0 ft. scribed ¼ S21 CSBT
 25" W.Oak bears East 459.8 ft. scribed ¼ S22 CS BT.

Milo E. Godfrey, Deputy - Mike Stone - June 1964 C.S. 52/87-34

Found - ¾" I.P. at corner, also rotten scribed stake lying on ground.
 25" W.Oak East, 459.8 ft. alive & in good condition scar plain.
 The NW tree is now down.
Drive Auto cam shaft alongside ¾" pipe at corner.
New BT - 13" W.Oak S.85°W., 341.5 ft. mkd. ¼ S 21 CS BT.
 This tree is on top of small hill.