

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. for Sec. 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Ben B. Irving - A.R. Evans - County Surveyors Office November 1949 - C.S. File 43/167 and M 16-25</p> <p>-----</p> <p>Set - Auto Axle, 6" flange. NW Cor. of concrete barn foundation bears S.80°E., 84.5 ft.</p>
<p>Milo E. Godfrey, Deputy - Mike Stone - June 1964 C.S. File 52/87-29</p> <p>-----</p> <p>Found - Axle with flange as set by Evans in 1949. Concrete barn foundation still OK. No trees available for scribing. Corner is in garden 1.5 ft. N of fence corner, fences running South and West.</p>
<p>Douglas Co. Surveyors Office - Randall Smith; Stephen Flause May 4, 1990 - C.S. 64/9-1</p> <p>-----</p> <p>Found - A 6¾" Auto axle flange with a 3½" dia raised center hub. (Rec. 6" flange) found flush with ground. NW cor. of concrete barn foundation bears S.82½°E., 84.5 ft. (Rec. S.80°E., 84.5 ft.). Fence corner noted by Godfrey is knocked over.</p> <p>New - 5" dia. Ash double blazed & scribed "C ¼ S3 CS BT" bears S.65½°W., 47.0 ft. 6" dia. Ash double blazed & scribed "C ¼ S3 CS BT" bears N.63°E., 97.4 ft. 2 ft. sq concrete footing for electric generating windmill, center bears N.50½°W., 168.6 ft. Corner lies near the intersection of a south and west running fence lines.</p>
<p>DCSO-GIS Corner visitation - 7/20/2004 - Typed: 1/27/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - 6.75" Comment - OK</p>