

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION Sec Cor for 31 & 32; 5 & 6 of T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, under Contract #57 dated April 12, 1855 (DCSO records, Vol. 11 Page 4595)

Set post, cor. sec. 31, 32, 5 & 6, from which
A Fir 24" dia., bears N.28°W., 72 lks. dist.
A Fir 10" dia., bears N.16°E., 262 lks. dist.
A Fir 10" dia., bears S.5°E., 198 lks. dist.
A Fir 18" dia., bears S.75°W., 65 lks. dist.

GLO survey by S.C. Flint, under Contract #392 dated May 26, 1881 (DCSO records, Vol. 11 Page 4622)

Corner to secs. 31, 32, 5 and 6. Old post gone. Witness trees all found. Made new laurel post and set firmly in the ground, from which
A Fir 24" dia., bears N.28°W., 72 lks. dist.
A Fir 10" dia., bears N.16°E., 262 lks. dist.
A Fir 10" dia., bears S.5°E., 198 lks. dist.
A Fir 18" dia., bears S.75°W., 65 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy; Milo Godfrey; Clete Putnam - Jan. 1961 - C.S. File 49/79-27

Found - Orig. 18" now 42" Fir stump S.75°W., 42.9 ft. shows good scribing "BT".
Orig. 24" now 48" Fir stump, checks bearing & dist. for NW BT.
Orig. SE BT, would be in existing roadway.
Orig. 10" now 28" Fir, checks bearing & distance for NE BT.

Set Brass cap at corner mkd. County Surveyors S31|S32 T26S
Office, 1961 S 6|S 5 T27S R7W

Note: 3/4" Pipe bears S.43°W., 2.5 ft.
New BTs - 21" Fir bears N.43¼°E., 41.5 ft. scribed S32 T26S R7W CS BT.
24" R.Fir bears S.9°E., 65.3 ft. scribed S5 T27S R7W CS BT.
No tree near West of corner.

BLM resurvey, Fd. Co. BC & 4 BTs. (DCSO records, Vol. 37 Pgs. 15159-60)

continued next page

