

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - S. C. Flint under Contract #392 dated May 1881  
(DCSO records, Volume 11 Page 4632)

-----  
Set Hemlock post for ¼ sec. cor., 3 ft. long, 3" sq., from  
which

A Fir 20" dia., bears N.30°W., 13 lks. dist.

A Fir 10" dia., bears N.20°E., 13 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy -  
May 13, 1957 - C.S. File 47/191-2

-----  
Found - Sq. stake at corner and both BTs, now dead.  
(Originals), now same size as when scribed and  
each BT bark scribed.

Set An Iron pipe with brass cap at corner marked:

¼ S 30 | S 29 T26S R7W County Surveyors Office, 1957  
Blazed and scribed two trees:

12" W.Fir N.27°E., 59.2 ft. mkd. ¼ S29 CS BT.

10" W.Fir S.33°W., 9.5 ft mkd. ¼ S30 CS BT.

Bureau of Land management resurvey by Peterson, Berry etal,  
under Group #'s 744 and 838, Survey May, 1971/Aug. 1974  
(DCSO records, Volume 37 Pages 15185-86)

-----  
The 1/4 Cor., perpetuated and recorded by the County Surveyor,  
in 1959, monumented with an I.P. 1¼" dia., firmly set, pro0  
jecting 12" above ground, with brass cap properly marked.

from which the remains of the original bearing trees

A Fir snag 10" dia. bears N.20°E., 13 lks. dist.,  
no marks visible.

A Fir snag, 22" dia., bears N.30°W., 13 lks. dist.,  
with fragmentary scribe marks visible on bark blaze.

and the remains of bearing trees mkd. by the County

A Fir snag 14" dia., bears N.27°E., 90 lks. dist.,  
with scribe marks BT visible on open blaze.

A root hole, bears S.33°W., 14 lks. dist., with a down  
Fir alongside, 10" dia., with scribe marks 1/4 S30  
BT visible on decayed blaze.

and new bearing tree

A fir 6" dia., bears N.28½°E., 35½ lks. dist., mkd.  
1/4 S29 BT.

A Fir 6" dia., bears S.54°W., 16 lks. dist., mkd.  
1/4 S30 BT.

Add marks BLM 1974 to brass cap.

continued next page

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 29 & 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor & Robert Browning, Surveying Technician under Group #1990, surveyed 2001/2002 (DCSO rec. Vol. 54 pg(s) 21020-1)

-----  
The ¼ sec. cor. of secs. 29 & 30, monumented with an iron pipe, 1½" dia., firmly set, projecting 14" above ground, with brass cap mkd. COUNTY SURVEYORS OFFICE

T 26 S R 7 W  
1/4 S 30 | S 29  
1957

from which the remains of original bearing trees  
A decayed fir stump, size indeterminate, bears N.20°E., 8.6 ft., with no marks remaining.  
A decayed fir snag, 21" dia., bears N.30°W., 8.6 ft., with no marks visible.  
and the remaining bearing tree mkd. by Byron, in 1957  
A fir, 17" dia., bears N.27°E., 59.4 ft., with a healed double blaze. (Record, fir snag)  
and BTs mkd. by Peterson, Berry, Popken, and Wofford  
A fir, 13" dia. bears N.28½°E., 23.4 ft. w/a healed blaze  
A fir, 16" dia. bears S.54°W. 10.6 ft. with a healed blaze  
The Peterson, Berry, Popken, and Wofford record erroneously shows this brass cap as being marked 1959.