

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - S. C. Flint, under Contract #392 dated May 1881
(DCSO records, Volume 11 Page 4636)

Set a Cedar post for ¼ sec. cor. 3 ft. long and 4 sq., from
which

A Cedar 24" dia., bears N.80°W., 21 lks. dist.,

A Fir 12" dia., bears S.12°W., 33 lks. dist.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone;
Jack Heritage - May/June 1966 - C.S. File 54/23-22

Found - Orig. 24" now 38", N.80°W., 13.9 ft. (alive), shows
faint bark scribe "¼S" on upper face and
fragmentary scribe on lower face.

Hole, approx. where SW orig. BT would have been

Set Brass cap at cor. mkd: County Surveyors Office, 1966 T26S ¼ $\frac{S\ 8}{S\ 17}$ R7W

New BTs - 13" D.Fir N.57°E., 3.9 ft. mkd. ¼ S8 CS BT.

16" D.Fir S.7°W., 17.2 ft. mkd. ¼ S17 CS BT.

Rebark scribe alongside orig. scribe, as follows:

38" Cedar N.80°W., 13.9 ft. mkd. ¼ S8 CS BT.

Corner lies on South edge of bench.

Corner found OK, (1966 BC and 3 BTs) - by BLM resurvey,
Roseberry and Garrison, 1967 (DCSO records, Vol. 34 Page 14288)