

PRIMARY CORNER DESCRIPTION Sec. Cor. 15, 16, 21, 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 11 Page 4611)

-----  
Set post, cor. secs. 15, 16, 21 and 22, from which  
A Chinquapin 10" dia., bears S.80°W., 25 lks. dist.  
A Fir 8" dia., bears N.32°E., 15 lks. dist.  
A Fir 10" dia., bears N.52°W., 12 lks. dist.  
A Fir 10" dia., bears S.5°E., 41 lks. dist.

G.G. Stewart, Deputy - Wit: C.Crocker, Blumburg, Will Long; Carpenter - Dec. 1, 1922 Vol. 3 Page 131; M 2-8

-----  
Reset from one O.B.T. Others gone. Drove an Iron pipe & mkd. the following trees:  
Hemlock 24" dia., bears N.18°E., 46.2 ft.  
Hemlock 20" dia., bears N.57½°W., 24.0 ft.  
Fir 36" dia., bears S.50°W., 48.5 ft.

Bureau of Land Management resurvey, by Irving Zirpel & Leo Martin under Group #'s 350 and 357. Survey April-May 1959 (DCSO records, Volume 29 Page 12540)

-----  
The cor., perpetuated and recorded by G.G. Stewart in 1922, monumented with an iron pipe, 1" dia., 6" above ground, firmly set, at record bearing and distance from the only remaining original bearing tree:

A fallen Fir 30" dia., bears S.5°E., 41 lks. dist.  
and locally established bearing trees:  
A W.Fir 36" dia., bears N.18°E., 70 lks., bark scribed S15 CS BT.  
A sawed Fir stump 44" dia., bears S.50°W., 73½ lks., no marks visible.  
A W.Fir 30" dia., bears N.57½°W., 36½ lks. bark scribed S16 CS BT.

At the corner point, set an iron post, 28" long 2½" dia., 26" in the ground, with brass cap mkd:

T26S	R7W
S 16	S 15
S 21	S 22
1959	

from which new bearing trees  
A W.Fir 16" dia., bears S.0°15'E., 82 lks. mkd. T26S R7W S22 BT.  
A W.Fir 16" dia., bears S.37°W., 51 lks. dist., mkd. T26S R7W S21 BT.

Deposit the Iron pipe alongside the iron post.  
The corner falls 1 lk. SW. of a fence corner from which fences extend N. and E (Cont. Next Page)

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 15, 16, 22 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - March 1966 - C.S. File 54/23-6

-----  
Found - 1959 Cadastral brass cap & I.P. by Stewart.  
All BTs down, dead or gone completely.  
New BTs - 8" W.Fir N.44°E., 12.7 ft. mkd. T26S R7W S15 CS BT.  
9" Cedar N.43°W., 21.2 ft. mkd. T26S R7W S16 CS BT.  
5" W.Fir S.41°E., 11.5 ft. mkd. S22 CS BT  
This corner lies at fence corner, fences N. & E.  
No tree available to SW.

Bureau of Land Management resurvey by Peterson, etal, under Group #'s 744 and 838. Survey May 1971-Aug. 1974 (DCSO records Volume 37 Pages 15174-75)

-----  
Cor. monumented with an iron post 2½" dia., firmly set, projecting 10" above ground, with brass cap mkd.

T 26 S R 7 W  
S 16 | S 15  
S 21 | S 22  
1959

from which a bearing tree by Zirpel and Martin, in 1959:  
A Fir 36" dia., bears N.18°E., 70 lks. with scribe marks  
T26S R7W S15 CS BT visible on open blaze.  
and a new bearing tree:  
A Fir 6" dia., bears S.21°W. 30 lks. mkd. T26S R7W S21 BT  
A Hemlock 8" dia., bears N.54°W., 14 lks. mkd. T26S R7W  
S16 BT.

Jan 1994 - by Harold Stockhoff - M118-23 - Fd No tag on W. Fir BT, D. Fir BT now stump.

Ronald L. Rice, Ward NW - Dec. 2009 - M 160-20

-----  
Found - 3¼" BLM BC dated 1959 with the following accessories  
20" I.Cedar bears N.43°W., 21.2' - healed face.  
18" W.Fir bears N.44°E., 12.7' - healed face.  
16" W.Fir (Rec hemlock) bears N.54°W., 9.2' healed face.  
14" D.Fir bears S.21°W., 19.8' - healed face.  
14" W.Fir bears S.41°E., 11.5' - healed face.