

TOWNSHIP 26 RANGE 07 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original, Dennis Hathorn, under Contract #57 dated April 12 1855 (DCSO records, Volume 11 Page 4606)

Marked Black Oak 14" dia., for cor. of secs. 10, 11, 14 and 15, from which

- A B.Oak 10" dia., bears S.10°W., 7 lks. dist.
- A B.Oak 12" dia., bears S.70°E., 38 lks. dist.
- A B.Oak 6" dia., bears N.21°W., 15 lks. dist.
- A B.Oak 6" dia., bears N.75°E., 38 lks. dist.

G.G. Stewart, Deputy Co. Surveyor - Wit: C. Crocker; Blumburg; Will Long; Carpenter - Dec. 1, 1922 - Vol. 3 Pg. 131; M 2-8

Reset from old 18" Black Oak called for as corner. Only stub of corner tree is left and BTs are gone. Marked new BTs as follows:

- B.Oak 16" dia., bears N.68°W., 21 ft.
- B.Oak 24" dia., bears S.77½°W., 60.5 ft.
- Cedar 8" dia., bears S.57½°E., 23.5 ft.
- Laurel 4" dia., bears N.71°E., 35.0 ft.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - March 1966 - C.S. File 54/23-11

Found - Fragments of stump of Orig. corner tree.
16" now 19" B.Oak N.68°W., 21.0 ft. shows "CS" on unhealed blaze, tree alive.
24" B.Oak S.77½°W., 60.5 ft., down & rotting. Open and find "S1 CS B" reverse scribe.
8" now 20" Cedar S.57½°E., 23.5 ft. shows scar, alive, do not open.
4" now 11" Laurel N.71°E., 35.0 ft. shows faint scar, alive, do not open.

No trace of original BTs.

Set Brass cap at cor. in E-W fence mkd: S 10 | S 11 T26SR7W
County Surveyor's S 15 | S 14
Office, 1966

New BT - 5" D.Fir S.34°W., 13.5 ft. mkd. S15 CS BT.
Corner lies 23.0 ft. West of fence corner, fences N - E. & W.

Fd as per M160-20 - Set 6 ft steep post 2' east - 1/2022 - D. Edwards - M180-39

Fd. as per record 11/2023 by D. Edwards 2023-0037