

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T26-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by - A. R. and S.C.Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 11 Page(s) 4647)

Cor. to secs. 25, 30, 31 and 36.
Set Hemlock post 4 ft. long, 4" sq., from which
A Fir 10" dia., bears S.10°E., 17 lks. dist.
A Fir 15" dia., bears S.45°W., 7 lks. dist.
A Fir 8" dia., bears N.8°W., 18 lks. dist.
A Fir 6" dia., bears N.45°E., 23 lks. dist.

GLO resurvey by John W. Meldrum, Deputy Surveyor, under Contract #662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4720)

Set Cedar post 3 ft. long, 4" sq., 24" in the ground for cor., marked T26S S30 on NE.; R8W S31 on SE.; S36 on SW.; and R9W S25 on NW. faces, with 5 notches on N. and 1 notch on S. edges, from which
A Fir 10" dia., bears N.59°E., 163 lks. dist. mkd. T26S R8W S30 BT.
A Fir 10" dia., bears S.18°E., 61 lks. dist. mkd. T26S R8W S31 BT.
A Fir 15" dia., bears S.85°W., 358 lks. dist. mkd. T26S R9W S36 BT.
A Fir 12" dia., bears N.77°50'W., 358 lks. dist. mkd. T26S R9W S25 BT.
From this cor., the old cor. which is almost obliterated by fires, only the charred stumps of the BTs remaining; the one on the SE. still showing the letter T on lower blaze; all other marks gone, bears N.49°15'W., 96 lks. dist.

Arthur Boyer - Wit: Harvey Eppstein; Donald Wood; Glenn Wood - Oct. 8, 1959 - C.S. File 51/50

Searched for the sec. cor., and found:
A Fir snag in S.36 on the bark of which was distinct signs of the blazes for the wit. tree, but the inside of the bark marking was rotten wood where the scribe would have been.
Also found the snag of the wit. tree in S. 31 which showed signs of having been axed out for the markings.
Fire destroyed most of the trees here. When the corner was set from these two trees, the brgs. and dists. matching, the corner fell S.45°E., 18 ft. from a point measured North 2640 ft. from the ¼ cor. bet. 31 & 36, using a 20° decl., and 2.9 ft. N. of a point which is W. 2659 ft. from the S. ¼ cor. of 30, using 20° decl.
(Cont. Next Page)

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31; 25 & 36, T26-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Drove a 4" x 4" Fir post for the corner, an blazed and scribed:

18" Fir N.77°E., 4.0 ft. mkd. S30 T26S R8W 1581 BT.

12" Fir S.30°E., 20 ft. mkd. S31 T26S R8W 1581 BT.

24" Fir S.37°W., 26.6 ft. mkd. S36 T26S R9W 1581 BT.

24" Fir N.64°W., 7.9 ft. mkd. S25 T26S R9W 1581 BT.

(All measurements to the center of trees.)

This corner is on the E. slope of a N. & S. ridge; 50 ft. S. of top of ridge; about 100 ft. W. of small creek. A vertical rock bluff is about 100 ft. to 150 ft. E., running E. & W. with sec. line.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #638, surveyed May\July 1967 (DCSO records Vol. 34 Page(s) 14175-76)

The Sec. Cor., determined at record bearing and distance from the remaining original bearing trees:

A rotted and burned Fir stump 18" dia., bears S.18°E., 61 lks. dist., with no marks remaining.

A Fir snag 32" dia., bears S.85°W., 358 lks. dist. with no marks visible on opened and rotted blaze.

and bearing trees mkd. and recorded by Boyer in 1959:

A Fir 20" dia., bears N.78°E., 6 lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

A Fir 15" dia., bears S.34°E., 30 lks. dist. with fragmentary scribe marks visible on partially healed double blaze.

A Fir 25" dia., bears S.35°W., 39 lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

A Fir 28" dia., bears N.65°W., 12 lks. dist., with fragmentary scribe marks visible on partially healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:

T 26 S
R 9 W R 8 W
S 25 S 30
S 36 S 31
1967