

PRIMARY CORNER DESCRIPTION Cor. Secs. 7, 18; 12, 13 T26-9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by A.R. & S.C. Flint, Deputy Surveyors under Contract No. 392, dated May 26, 1881 - (DCSO records Vol. 11 Page(s) 4646)

Cor. to secs. 7, 12, 13, & 18 from which
A W.Fir, 40" dia., bears S.15°W., 36 lks.
A Cedar, 30" dia., bears S.35°E., 14 lks.
A Hemlock, 12" dia., bears N.12°W., 14 lks.
A Fir, 48" dia., bears N.44°E., 27 lks.
Post to cor. 4 ft. long, 4" sq. firmly set in the ground.

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4723-4)

Set cedar post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 7, 12, 13 & 18, marked T 26S S7 on NE, R8 S18 on SE, S13 on SW. and R9W S12 on NW faces, with 2 notches on N & 4 notches on S edges, from which
A fir, 48" dia., bears N.53°E., 5 lks., mkd T26S R8W S7 BT
A hemlock, 20" dia., bears S.55°E., 62 lks., mkd: T26S R9W S18 BT.
A cedar, 20" dia., bears S.55°45'W., 74 lks., mkd: T26S R9W S13 BT.
A fir, 48" dia., bears N.45°30'W., 75 lks., mkd: T26S R9W S12 BT.
From this corner the old cor. bears S.16°E., 364 lks., which is a post, still standing & witnessed as follows:
A hemlock, 40" dia., (given as a W.Fir in field notes) bears S.15°W., 34 lks., (given as 36 lks., in field notes)
A cedar, 30" dia., bears S.45°E., (given as S.35°E., in field notes) 14 lks.
A hemlock, 12" dia., bears N.12°W., 14 lks., (same as in field notes)
A fir, 48" dia., bears N.44°E., 27 lks., (same as in field notes)
I destroy the post & obliterate the marks on the old BTs.

Weyerhaeuser reports received June 17, 1970 C.S. 55/155A-5

Date: 10/61
20" Ced "W" nail-tag N.73½°E., 36.3 ft.
48" Ced "W" nail-tag S.33½°E., 52.3 ft.
36" Ced "W" nail-tag S.55¾°W., 48.8 ft. OBT
64" DF "W" nail-tag N.45½°W., 49.7 ft. OBT
By Whom: Stevens, Kauffman, Humphreys, Kunkle