

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Pages 4696-7)

Set a fir post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on N face, from which

 A fir, 15" dia., bears S.44°E., 354 lks., mkd: ¼ S BT.
 (Out of limit)

 No living trees within limit.

 Dig pit, 18x18x12, 5 ft. SE of cor.

 A fir, 36" dia., bears N.71°E., 268 lks., mkd: ¼ S BT.

Arthur Boyer - Wit: Harvey Eppstein; Donald Wood; Glenn Wood
- Oct. 8, 1959 - C.S. File 51/50

Found - Lower scribed blaze on Stump of Wit. Tree in Sec. 30
Rotted Stump of Tree in Sec 31, both Orig. Trees &
from them, located corner driving a 1"x30" Steel
Shaft here.

New - 18" Fir, N.44°W. 25.0 ft. scribed ¼ S30 1581 BT.
8" Fir S.31°W. 16.3 ft. scribed ¼ S31, 1581 BT.
(Measurements to center Trees)

Dependent resurvey by Peter A. Peterson, Cadastral Surveyor,
under Group No. 638, surveyed May/July 1967 - (DCSO Records
Vol. 34 Page(s) 14182)

The sec. cor. of secs. 30 & 31, perpetuated & recorded by
Boyer, in 1959, with a steel rod, 30" long, 1" dia., firmly
set 20" in ground, from which the original bearing trees:

 A sawed fir stump, 62" dia., bears N.65°E., 268 lks., with
 fragmentary scribe marks visible on opened blaze.
 (Record, N.71°E.)

 A fir root crown, 20" dia., bears S.44°E., 354 lks., with
 no marks remaining.

and trees marked by Boyer

 A sawed fir stump 24" dia. bears N.44°W., 38 lks. w/frag.
 scribe marks visible on partially healed blaze.

 A fir, 10" dia., bears S.31°W., 25 lks., with healed
 double blaze.

At the Corner point

Set an iron post, 28 ins, long, 2" dia., 24" in the ground,
with brass cap marked

¼ $\frac{S\ 30}{S\ 31}$
T26S R8W
1967

from which

 A fir, 14" dia., bears N.75°W., 35 lks., mkd: ¼ S30 BT.
 Deposit the steel rod alongside the iron post.