

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 28, 29, 32, & 33

|             |                   |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4672-3)

-----

Set a yew post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 27, 28, 33, & 34, mkd T26S S27 on NE, R8W S34 on SE, S33 on SW & S28 on NW faces with 3 notches on E and 1 notch on S edges, from which

- A fir, 30" dia. bears N.42°E. 57 lks. mkd: T26S R8W S27 BT
- A fir, 36" dia. bears S.63°E. 60 lks. mkd: T26S R8W S34 BT
- A fir, 40" dia., bears S.14°W., 134 lks., mkd: T26S R8W S33 BT.
- A fir, 36" dia. bears N.31°W. 58 lks, mkd: T26S R8W S28 BT

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4716)

-----

Correction of surveys as ordered by the Commissioner of the GLO under date of March 18, 1898:  
Intersect Cor. to Secs. 27, 28, 33 & 34, marked as reported by the Examiner. I erase the Roman & mark with Arabic figures to wit: T26S S27 on NE, R8W S34 on SE, S33 on SW & S28 on NW faces, with one notch on S & 3 notches on E edges, from which the witness trees are as reported in orig. notes. I find the SW BT which the Examiner failed to find, Viz:

- A fir, 40" in dia., bears S.14°W., 134 lks.

Marvin C. Ramsey - For: J.H. Baxter - Aug 1959 - C.S. 51/41-1

-----

Set - An IP 3 ft. long 2" dia., 28" in the ground, mkd RS404 from which the OBTs:

- 30" Fir snag bears N.42°E., 57 lks. partial scribe mks.
- 36" Fir snag bears S.63°E., 60 lks. partial scribe mks.
- 40" Fir snag bears S.14°E., 134 lks. mks burned out.
- 36" Fir snag bears N.31°W., 58 lks., mks burned out.

New - 14" Fir bears N.12°E., 44 lks., mkd: T26S R8W S27 RS404 BT.

- 16" Fir bears S.69½°E., 47 lks., mkd: T26S R8W S34 RS404 BT.
- 12" Fir bears S.66½°W., 9½ lks., mkd: T26S R8W S33 RS404 BT
- 18" Fir bears N.10½°W., 63 lks., mkd: T26S R8W S28 RS404 BT.

continued next page

1

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Cor Secs 28, 29, 32, & 33

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Bruce Shaner - For: Hub Lumber Co. - June 24, 1974 - RM 2-63

-----  
Found - 2" iron pipe with brass washer attached mkd. "RS 404  
(1959) from which A;  
36" orig D.Fir BT rotted snag, bears N.42°E. 37.6 ft  
36" orig. D.Fir BT rotted snag bears S.63°E. 39.6 ft  
40" orig. D.Fir BT rotted snag bears S.14°W. 88.4 ft  
42" orig. D.Fir BT rotted snag bears N.31°W. 38.3 ft  
20" D.Fir BT face grown over, bears N.8°W., 42.1 ft  
16" D.Fir BT face grown over, bears N.12°E., 29.0 ft  
18" D.Fir BT face grown over, bears S.72°E., 31.4 ft  
14" D.Fir BT opened & found scribes, bears S. 62 W.,  
6.4 ft.

Dependent resurvey by John P. Farnsworth, Cadastral Surveyor,  
under Group No. 1065, surveyed June/July 1981 - (DCSO Records  
Vol. 44 Page(s) 17037-8)

-----  
The cor. of secs. 27, 28, 33, & 34, perpetuated & recorded by  
Ramsey, in 1959, monumented with an iron pipe, 2" dia.,  
loosely set, projecting 8" above ground, with brass washer  
marked RS404, on top, from which the remains of the OBTs

A decayed fir snag, 23" dia., bears N.42°E., 57 lks. no  
marks remaining.

A decayed fir snag, 35" dia., bears S.63°E., 60 lks. no  
marks remaining.

A decayed fir snag, 45" dia., bears S.14°W., 141 lks. no  
marks remaining. (Record, 134 lks.)

A decayed fir snag, 33" dia., bears N.31°W., 58 lks. no  
marks remaining.

and bearing trees mkd. by Ramsey

A fir, 18" dia., bears N.12°E., 44 lks. with healed blaze.

A fir, 20" dia., bears S.72°E., 47 lks. with healed blaze.

A fir, 15" dia., bears S.62°W., 9½ lks. with illegible  
scribe marks visible on opened blaze.

A fir, 22" dia., bears N.10½°W., 63 lks. with healed blaze

At the corner point

Set an iron post, 28" long, 2½" dia., 18" in the ground, to  
solid rock & in a mound of stone, 3 ft. base to top, with  
brass cap marked:

T26S R8W  
S 28 | S 27  
S 33 | S 34  
1981

Reset the iron pipe alongside the iron post.