

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4676-7)

Set a fir post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 15, 16, 21, & 22, mkd T26S S15 on NE, R8W S22 on SE, S21 on SW & S16 on NW faces with 3 notches on S and E edges, from which

- A fir, 30" dia., bears N.83°E., 29 lks., mkd: T26S R8W S15 BT.
- A myrtle, 10" dia., bears S.47°E., 58 lks., mkd: T26S R8W S22 BT.
- A dogwood, 7" dia., bears S.53°W., 85 lks., mkd: T26S R8W S21 BT.
- A fir, 30" dia., bears N.58°W., 17 lks., mkd: T26S R8W S16 BT.

Triangle Engineering Co. Nick Juliano - May 1972 - M44-79 & C.S. File 55/251

Found - 50" Fir, N.83°E., 19.1 ft. scar visible.
12" Myrtle, S.47°E., 38.3 ft. rotted face.
Ground Depression, N.58°W., 11.2 ft.
Post Gone.

Set - 1½" Iron pipe with brass cap. Referenced with "W" nails and plates.

New BTs- 44" Fir, S.61°W., 79.9 ft.
14" W. Fir, N.78°W., 35.5 ft.
22" Hemlock, S.44°E., 53.6 ft.