

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4681)

Set cedar post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on N face, from which
A fir, 48" dia., bears N.20°W., 104 lks., mkd: ¼ S BT.
An alder, 4" dia., bears S.45½°W., 62 lks., mkd: ¼ S BT.

BLM dependent resurvey by Jack W. Bowder, Cadastral Surveyor, under Group #350, surveyed May 1977 - (DCSO records Vol. 40 Page(s) 15954)

The ¼ sec. cor. of secs. 3 & 10, determined at record bearing & distance from the remaining original bearing tree:
A fir, 52" dia., bears N.20°W., 104 lks., with fragmentary scribe mks visible on weathered bark blaze.
At the corner point
Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap mkd.
T26S R8W
_____ ¼ S 3
_____ S 10
_____ 1977
from which new bearing trees
A fir, 20" dia., bears N.66½°E., 32 lks., mkd. ¼ S3 BT.
A fir, 21" dia., bears S.75°E., 2 lks., mkd. ¼ S10 BT.